CARVERTICAL

Ford Transit

VIN: WF0FXXTTGFFE53498 Diesel 2015

Generated on 05/14/2025, 02:08 PM

Scan for full report

Purpose ✓ Looks good

Odometer ⚠ Needs attention

Legal status ✓ Looks good

Damage ⚠ Needs attention

+31 **Data sources**
We checked 900+ data sources in **35 countries**

Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

No issues found
No records of vehicle being used in irregular manner

Here's what we checked:

Taxi ✓ No record found No evidence of being used as a taxi

Transport ✓ No record found No evidence of being used as a transport vehicle

Rental ✓ No record found No evidence of being used as a rental vehicle

Police ✓ No record found No evidence of being used by police

Demo ✓ No record found No evidence of being used as a demo vehicle

Driving school vehicle ✓ No record found No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

No issues found
We didn't find any records that the vehicle was stolen.

Note
Police database stolen vehicle check completed in **11 countries**: +5

Here's what we checked:

Currently wanted as stolen ✓ No record found

Stolen in the past ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle **check completed in:**

- Lithuania
- Czechia
- Hungary
- Denmark
- United States
- Romania
- Slovakia
- Canada
- Italy
- Slovenia
- Sweden

Odometer

Are there signs of mileage rollbacks or discrepancies?

Beware
This vehicle may have a fake mileage!

Note
- Last known mileage: 217,902 km
- Average mileage for similar models: 230,901 km
- 8 mileage records found

⚠ Rollback



Odometer records	
01/2015	10 km
11/2015	14 km
05/2017	126,191 km
11/2017	197,200 km
06/2018	259,250 km

Odometer records		
09/2018	312,831 km	
07/2023	379,505 km	
03/2025	217,902 km	⚠ Odometer Rollback

Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

No issues found
No records about the legal status of this vehicle were found

Legal

Technical inspection (MOT) Passed 03/2020 **Romania** Has successfully passed technical inspection
Valid until 03/2022

Scrap ✓ No record found No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

Beware
We found 2 records for this vehicle

Note
Mild damages normally won't impact a vehicle's safety or leave structural issues

Damage records



Front damages: **Front / Windshield**

01/2017 **Romania**

Assessment

Sides affected
Front

Estimated Repair Cost
€501 – €1,500

Possible Cause
Unknown

Damage Groups
Glass



Rear damages: **Rear right / Bumper**

01/2018 **Romania**

Assessment

Sides affected
Rear

Estimated Repair Cost
€501 – €1,500

Possible Cause
Unknown

Damage Groups
Exterior body parts Glass

Disclaimer: Most damage records are related to accidents, but that's not always the case. Some records come from other sources like body shops, damage claims, auctions, or vehicle inspections. These records show that the vehicle's condition was assessed, even if it wasn't due to an accident.

Damage Glossary

Assessment
Assessment is the process of evaluating the extent of damage to a vehicle. It involves inspecting the vehicle to determine what repairs are needed, estimating the costs, and deciding whether the vehicle is repairable or considered a total loss.

Estimated Repair Cost
Once an incident related to a vehicle is assessed, damage data providers calculate the repair cost and present it in the currency of the country where the damage was evaluated. Therefore, this may not align with your expectations. The reasons for this may include:

- The country or state where damage to the vehicle was assessed may have higher/lower servicing costs compared to your country (spare part prices and labor prices differ between countries)
- The cost is calculated for repairs at an official service station (which is typically on the expensive end)

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

No issues found
Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

Note
- Last known selling price: €12,300
- Average market price for such vehicle: €11,503
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Ford Transit 2015 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price	Average price	Highest price
€9,906	€11,503	€14,871

Market price history



Price records	
03/2025	€12,400
04/2025	€12,300

Emissions

How much CO2 emissions do vehicles of this model/year produce?

carVertical Insight
This vehicle has high emissions. That could mean higher emission taxes. Check local regulations to avoid surprises.

CO_2 emissions

Emission CO_2 g/km

- Up to 120
- 120 - 140
- 140 - 155
- 155 - 165
- 165 - 190
- 190 - 225
- 225 +

Your vehicle CO_2 emissions
178 g/km

Specs

What specs and equipment are on record for this vehicle?

Note
Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

Make	**Ford**
Model	**Transit**
Body type	**Multi-purpose vehicle**
Manufacture year	**2015**
Model year	**2015**
Powertrain displacement	**2.2 L**
Powertrain power	**114 kW (153 hp)**
Fuel type	**Diesel**
Transmission type	**Manual**
Drive type	**FWD**
Color	**Blue**
Engine code	**CVF5**
Category	**m1**
Type Approval	**e11*2007/46*0801*01**
Gross weight	**5,100 kg**

Timeline

8 records found

The timeline of records for this vehicle

Records

01/2015 Country unknown
Was manufactured
The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

11/2015 **Romania**
Was registered
The record represents an administrative event. This could be related to a change of ownership, documents, etc

01/2017 **Romania**
Assessment detected ⚠
We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

11/2017 **Romania**
Was inspected
A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

01/2018 **Romania**
Assessment detected ⚠
We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

03/2020 **Romania**
Was inspected
A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

03/2025 **Poland**
Was on sale
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

04/2025 **Poland**
Was on sale
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

+31 **Data sources**
We checked 900+ data sources in **35 countries**