
**Renault Mégane**

VIN: VF1RFB00865128823


Gasoline

2020


Generated on 03/31/2025, 10:39 AM

**Purpose**


✓ Looks good

**Odometer**


✓ Looks good

**Legal status**

✓ Looks good

**Damage**


✓ Looks good

**Data sources**

We checked 900+ data sources in **35 countries**


Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

**No issues found**


No records of vehicle being used in irregular manner

Here's what we checked:

**Taxi**


✓ No record found

No evidence of being used as a taxi

**Transport**


✓ No record found

No evidence of being used as a transport vehicle

**Rental**


✓ No record found

No evidence of being used as a rental vehicle

**Police**


✓ No record found

No evidence of being used by police

**Demo**

✓ No record found

No evidence of being used as a demo vehicle


**Driving school vehicle**

✓ No record found


No evidence of being used as a driving school vehicle


Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?


**No issues found**

We didn't find any records that the vehicle was stolen.


**Note**

Police database stolen vehicle check completed in **8 countries**:  +2

Here's what we checked:

**Currently wanted as stolen**


✓ No record found


**Stolen in the past**


✓ No record found


Current status unknown


Police database stolen vehicle **check completed in:**


**Slovakia**


**Slovenia**


**Czechia**

**Romania**

**Italy**


**Hungary**

**Sweden**


**Denmark**

Odometer

Are there signs of mileage rollbacks or discrepancies?


**Note**

- Last known mileage: 4,850 km
- Average mileage for similar models: 61,284 km
- 2 mileage records found




Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

**No issues found**


No records about the legal status of this vehicle were found

Legal

**Technical inspection (MOT)**

✓ No record found

No technical inspection records found

**Scrap**

✓ No record found


No record that vehicle was marked as scrapped

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

**No issues found**


Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

**No issues found**

Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

**Note**

- Average market price for such vehicle: €15,955
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Renault Mégane 2020 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price


€14,718

Average price

€15,955


Highest price

€17,816




Specs & equipment

What specs and equipment are on record for this vehicle?


**Note**

Check whether the specs and equipment of this vehicle match the facts given by the seller.


Identification and technical specifications

**Make**


Renault

**Model**


Mégane

**Description**


Mégane 4 (Xfb)

**Body type**


Hatchback

**Manufacture year**


2020

**Powertrain displacement**


1.8 L

**Powertrain power**


221 kW (296 hp)

**Fuel type**

Gasoline

**Number of doors**

5

**Number of gears**

6

Equipment

As received from the manufacturer

ACCESSORY SOCKET

WITH ACCESSORY SOCKET 2 (PRIAC2)

ADDITIONAL SENSING INFORMATION

RS MONITOR LEGACY (TATDB1)

AIR CONDITIONING TYPE

NON-HEATING WINDOW-WASHER (LAVNCH)

AIRBAG CANCEL

DECONNEX AIRBAG PASS (AIRBDE)

ANTI-THEFT DEVICES

EQUIPMENT LEVEL OF ALARM (PREALA)

BATTERY POWER TRACTION

WIHTOUT BATTERY ENERGY (SSCABA)

BLIND SPOT DETECTION

WITHOUT DECTECTOR BLIND S (SDANGM)

BRAKING ASSISTANCE

BOOSTER EMERGENCY BRAKING (AFURGE)

CHASSIS TYPE

SPORT WHEEL BASE (CHCUP1)

COMMERCIAL IDENTITY

COMPLEMENTARY OBJECT (SAND26)

COMMERCIAL VERSION SUPPLEMENT 5

WO COMMERCIAL VERSION (VSNOR)

ADDITIONAL HEADLIGHTS

SIGNAL LIGHT RSC (PROJ01)

ADJUSTMENT OF FRONT SEAT BELTS

HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)

AIR PURIFIER

WITHOUT AIR PURIFIER (SPFAIR)

ANTI-LOCK BRAKING SYSTEM

WITH ANTI-LOCK BRAKING SYSTEM (ABS)

AUDIO CONNECTION

COMPLEMENTARY OBJECT (SAN786)

BLACK BOX EDR

WITHOUT BLACK BOX (SBONO1)

BRAKE CALLIPER

BRAKE CALLIPER RED (ETRP02)

CENTER CONSOLE

CONSOLE W STORAGE & ARMRE (CSRGAC)

COMBI METER

MID RANGE TFT 7" (TBANU2)

CUSTOMIZED VERSION SUPPLEMENT

BASIC COMMERCIAL VERSION (VNOR)

COMPACT DISC LOADER

WITHOUT COMPACT DISK PLAY (SCDCOF)

CONDITIONING

STANDARD PROTECTION (COND0)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION

TECHNICAL REG : RP00 (TLRP00)

DAYTIME RUNNING LIGHTS

DAYTIME RUNNING LIGHTS 2 (FDIU2)

DRIVER ATTENTION ALERT

WITHOUT PRESTATION (SPRDEN)

DRIVING MODE CONTROL

MULTI EXPERIENCE 1 (MLEXP1)

ELECTRIC TOLL COLLECTION

WO ELECTRONIC TOLL SYS SP (SSPTLP)

ELECTROMOTOR DOOR LOCKING

ELECTRIC DOOR LOCKING (CPE)

ELECTRONIC STABILITY PROGRAM

DIRECT STAB CON HILL ASST (ESPHSA)

ENGINE PRODUCTION PLANT

(N) BUSAN (SOUTH KOREA) (APV002_N)

FIRE EXTINGUISHER

WITHOUT FIRE EXTINGUISHER (SEXTIN)

FORWARD EMERGENCY BRAKING

WITHOUT URB ADV EM BRAKE (SSAEB5)

FRONT HEADREST TYPE

FRONT HEADREST 03 (ATAV03)

FRONT SEAT TYPE

FRONT SEAT TYPE N 03 (SGAV03)

FRONT TYRES

245/35 R19 (93)Y, 8.50 J 19 - 54 C1 E

GEARBOX (PRODUCTION PLANT)

(C) CLEON (FRANCE) (APV003_C)

HEAD UP DISPLAY (HUD)

WITHOUT PRESTATION (SPRHMD)

HEATED STEERING WHEEL

NO-HEATED STEERING WHEEL (VOLNCH)

HIGH BEAM ASSIST

COMPLEMENTARY OBJECT (NOG70)

INTERIOR COLOUR STYLING

INTERIOR HARMONY 01 (HARM01)

COUNTER UNIT

KILOMETRES (KM)

CUSTOMIZED VERSION

VERSION WITHOUT ADAPTATIO (SAN613)

DOOR OPENING REMOTE CONTROL TYPE

433 MHZ NORMAL DOOR OPENI (SOP03C)

DRIVER'S HANDBOOK

CROATIAN GLOVE BOX LITERA (NOTCRO)

DUST PROTECTION

WITH DUST KIT (KITPOU)

ELECTRIC VEHICLE OR MOTOR FUNCT

TYPE 01 ELECTRIC VEHICLEB (BATR01)

ELECTRONIC ARCHITECTURE

COMPLEMENTARY OBJECT (SANF88)

EMERGENCY CALL AND BREAKDOWN

WITHOUT CALL VIEWING (SSCALL)

EXTERIOR REAR VIEW MIRRORS

DOOR MIRRORS 04 (RET04)

FIRST AID KIT

WITHOUT FIRST AID KIT (SKTSEC)

FRONT AND REAR BODY CROSSMEMBER

WIHTOUT CROSSMEMBER (SSRCAR)

FRONT SEAT SUITABLE FOR CHILDREN

ISOFIX SEAT (ISOFIX)

FRONT SIDE AIRBAG

FRONT SIDE AIRBAG + HEADA (ABLAV1)

GEAR SHIFT INDICATOR

WITH GEAR SHIFT INDICATOR (AVGSI)

GEOGRAPHIC COUNTRY

GEO COUNTRY CROATIA (HRV01)

HEADLIGHT WASHER

WITHOUT HEADLIGHT-WASHER (SLAVPH)

HEATED WINDSHIELD

NON-HEATED WINDSCREEN (PBNCH)

HIGH MOUNTED STOP LAMP

WITH RAISED BRAKE LIGHT (FSTPO)

INTERIOR REAR VIEW MIRROR

REARVIEW MIRROR CHROMIUM (RETRCR)

INVARIANT PROCESS SHEET MODEL

MODEL ROUTING SHEET (XFB1B1)

LUGGAGE BOX

W/O LUGGAGE BOX (SRANCF)

MAKE OF TYRES

TYRE MAKE TYRES: UNMARKED FITT (BANAL)

MISCELLANEOUS BEN GT RS LINE E

WITHOUT PRESTATION (SPGTLE)

MISCELLANEOUS BEN GT RS LINE S

WITHOUT PRESTATION (SPGTLS)

NAVIGATION MAP

MAPPING SUPERIOR (MAPSUP)

ON-BOARD WARRANTY/SERVICES

SERVICES BOOKLET (RSANA1)

OPTIONAL REAR TYRES

245/35 R19 (93)Y, 8.50 J 19 - 54

PARKING ASSIST SYSTEM

B7M ENGINE TYPE NOT USED (ITPK1)

PASSENGER COMPARTMENT HEATING TYPE

AIR-CONDITIONING TYPE N3 (CA03)

PLANT ASSEMBLY LINE

ASSEMBLY LINE 1 (CHMONT)

PRESTATION SOCIETE

COMPLEMENTARY OBJECT (NOG76)

REAR CENTRE SEATBELT

3-POINT CENTRE SEATBELT (CMAR3P)

REAR REAR SCREEN WIPERS

WITH REAR SCREEN WIPERS (ELA)

REAR SPOILER

REAR SPOILER (BECQAR)

REAR WINDOW

HEATED REAR SCREEN (LAC)

ROAD SEVERITY

TYPE OF ROAD SEVERITY 1 (TRSEV1)

ROUTING SHEETS COUNTRY

THE BALKANS (BALK)

SEAT COVERS

FABRIC SEAT-LINING N 06 (DRAP06)

SEAT TRIMS

VELVET CLOTH (DRA)

SERVICE DONGLE

COMPLEMENTARY OBJECT (NOH14)

SPARE WHEEL

REPAIR INFLATION KIT (KTGREP)

SPECIAL BUILD (FACTORY)

SERIES VEHICLE (WITHOUT S (SERIE)

SPRUNG MASS/REAR AXLE

SPRUNG WEIGHT/REAR AXLE 1 (TAR17)

STEERING WHEEL MATERIAL

ALCAN RS LEATHER STEERING WHEEL (VLCUI6)

STEERING WHEELS

4 DRIVE WHEELS (4ROUDI)

SUSPENDED WEIGHT/FRONT AXLE

SPRUNG WEIGHT/FRONT AXLE2 (TAV24)

TECHNICAL EVOLUTION D

EVAP 2018 (TCHD0)

TECHNICAL EVOLUTION F

COMPLEMENTARY OBJECT (NOH20)

TURN SIGNAL LAMP

INDICATORS WITH SIDE REPE (AVREPL)

TYPE OF CLIMATE

TEMPERATE CLIMATE (TEMP)

TYPE OF HEADLIGHTS

LED HEAD LAMPS TYPE-3 (LEDH3)

TYPE OF SHOCK ABSORBERS

CONTEXT CRITERIOM (SAN285)

TYPE OF TYRES

STANDARD TYRE (PNSTRD)

TYRE PRESSURE DETECTION

TYRE PRESSURE DETECTION (DPRPN)

UNIVERSAL INTERCONNECT FUNCTION

TCU VER 0 GEN 2 (TCU0G2)

VARIOUS ADDITIONAL FEATURES

COMPLEMENTARY OBJECT (SAN482)

LANE KEEP

W/O LANE DEPARTURE WARNI (SDLIGM)

LUGGAGE RETAINING DEVICE

WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

MARKETING VERSION

COMMERCIAL VERSION (VEC481)

MISCELLANEOUS BEN GT RS LINE I

WITHOUT PRESTATION (SPGTLI)

MISCELLANEOUS BENEFITS TER

COMPLEMENTARY OBJECT (SAN503)

NAVIGATION/SMARTPHONE IMITATION

SMARTPHONE IMITATION (SPMIR)

OPTIONAL FRONT TYRES

245/35 R19 (93)Y, 8.50 J 19 - 54

OVERSPEED AUDIBLE WARNING DEVICE

WITHOUT EXCESS SPEED HORN (SASURV)

PARKING BRAKE TYPE

WITHOUT AUTOMATIC PARKING (SSFRPA)

PASSENGER COMPARTMENT THERMAL REQUIREMENT

WITHOUT PASSENGER COMPARTMENT THERMAL REQUIREMENT (STHABT)

PLANT MARKING FOR COMPLEX START

COMPLEMENTARY OBJECT (SAN592)

PROTECTION ELEMENTS

DR+AS AIRBAG (AIRBA2)

REAR HEADREST TYPE

REAR HEADREST TYPE 3 (ATAR03)

REAR SEAT TYPE

REAR SEAT N 02 (SGAR02)

REAR TYRES

245/35 R19 (93)Y, 8.50 J 19 - 54 C1 E

REAR WINDOW PINCH

ELECTRIC ANTI-PINCH (LVARAP)

ROOF RACK/BARS

NO ROOF BARS (SBARTO)

SEAT BELT REMINDER

SEAT BELT WARN TYPE 5 (ALOUCS)

SEAT HEATER AND COOLER

VEHICLE LIGHT CONVERSION

WO LIGHT ADAPTATION SVO (SANCML)

VEHICLE TRACKING SYSTEM

W/O SECURITY DEVICE (SDPSEC)

WATER PROTECTION

WITH RAIN FORD RIVER KIT (KITPGR)

WHEELS RIMS

TROPHY 19" WHEEL (RDIF22)

WIPER START-UP TYPE

AUTOMATIC LIGHTS + WINDSCREEN WIPER (ALEVA)

VEHICLE PRODUCTION PLANT

(E) PALENCIA (SPAIN) (APV001_E)

VEHICLE TRANSFORMATION

COMPLEMENTARY OBJECT (SAND30)

WHEEL RIM TYPE

19 ALUMINIUM WHEEL RIM (RALU19)

WINDOW TINT

DARK GLASS ON LATERAL WIN (VSTLAR)

WIRELESS PHONE CHARGE

WO TELEPHONY ACCES REFI (SREACT)

Timeline

1 record found

The timeline of records for this vehicle

Records

02/2020 Country unknown

Was manufactured

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.