

Nissan Juke

VIN: SJNFAAF15U7037618 Gasoline 2014

Generated on 04/03/2025, 11:47 AM



Purpose

Looks good



Odometer

Looks good



Legal status

Looks good



Damage

Looks good



Data sources +31 We checked 900+ data sources in 35 countries

Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

No issues found

No records of vehicle being used in irregular manner

Here's what we checked:

Taxi No record found No evidence of being used as a taxi

Transport No record found No evidence of being used as a transport vehicle

Rental No record found No evidence of being used as a rental vehicle

Police No record found No evidence of being used by police

Demo No record found No evidence of being used as a demo vehicle

Driving school vehicle No record found No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

No issues found

We didn't find any records that the vehicle was stolen.

Note

Police database stolen vehicle check completed in 11 countries: +5

Here's what we checked:

Currently wanted as stolen No record found

Stolen in the past No record found Current status unknown

Police database stolen vehicle check completed in:


- United States
- Romania
- Hungary
- Denmark
- Czechia
- Italy
- Sweden
- Canada
- Slovenia
- Slovakia
- Lithuania

Odometer

Are there signs of mileage rollbacks or discrepancies?

Note

- Last known mileage: 33,840 km
- Average mileage for similar models: 106,033 km
- 3 mileage records found



Odometer records

09/2014	11 km
08/2016	21,844 km
08/2017	33,840 km

Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

No issues found

No records about the legal status of this vehicle were found

Legal

Technical inspection (MOT) No record found No technical inspection records found


Scrap No record found No record that vehicle was marked as scrapped

Damage

Has this vehicle been damaged in the past? What was the value of the damages?

No issues found

Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

No issues found

Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

Note

- Average market price for such vehicle: €9,944
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Nissan Juke 2014 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price

€7,647

Average price

€9,944

Highest price

€11,006

Specs & equipment

What specs and equipment are on record for this vehicle?

Note

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

Make Nissan

Model Juke

Description F15 Juke

Body type Multi-purpose vehicle

Manufacture year 2014

Fuel type Gasoline

Transmission type Manual

Number of doors 4

Steering wheel placement RHD

Equipment

As received from the manufacturer

- 0 SUNROOF
- 2 TYRE 18" ALU PERSO
- 4 XENON
- 1 LEATHER SEAT
- 3 EXT PACK RED
- 5 ANTI-THEFT DEVICES

Safety

Does the vehicle have any manufacturer safety recalls? What is its safety rating?

Beware

1 recall found

carVertical Insight

This vehicle had a past recall, but the issue has been fixed. No further action is needed. Regular maintenance will help it stay safe on the road.

Recalls

Recall status: Solved

We found a recall announcement. The manufacturer has announced a recall for this particular vehicle.

Recall-number R1620

Description REAR O2 SENSOR OBD

Timeline

1 record found

The timeline of records for this vehicle

Records

09/2014 Country unknown

Was manufactured

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.



Data sources +31 We checked 900+ data sources in 35 countries