


Renault Master
VIN: VF1MA000X66530950 Diesel 2020
Generated on 05/20/2025, 04:10 PM



Scan for full report

Purpose
Looks good

Odometer
Looks good











Legal status
Looks good

Damage
Looks good

 **Data sources**
We checked 900+ data sources in **35 countries**

Photos
We found **46 photos** of this vehicle. Scan report QR code to see all.

10/2024





+36 photos


Purpose
Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual


No issues found
No records of vehicle being used in irregular manner


Here's what we checked:


 **Taxi** ✓ No record found No evidence of being used as a taxi

 **Transport** ✓ No record found No evidence of being used as a transport vehicle

 **Rental** ✓ No record found No evidence of being used as a rental vehicle


 **Police** ✓ No record found No evidence of being used by police

 **Demo** ✓ No record found No evidence of being used as a demo vehicle


 **Driving school vehicle** ✓ No record found No evidence of being used as a driving school vehicle


Theft
Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

No issues found
We didn't find any records that the vehicle was stolen.


Note
Police database stolen vehicle check completed in **11 countries:**  **+5**


Here's what we checked:


 **Currently wanted as stolen** ✓ No record found


 **Stolen in the past** ✓ No record found No past theft records found for this vehicle.


Police database stolen vehicle **check completed in:**


 Lithuania


 United States


 Slovakia


 Denmark


 Czechia


 Italy

 Romania

 Hungary

 Slovenia


 Sweden

 Canada

Odometer
Are there signs of mileage rollbacks or discrepancies?

Note

- Last known mileage: 43,936 km
- Average mileage for similar models: 133,036 km
- 3 mileage records found






| Date | Mileage (km) |
|---------|--------------|
| 12/2020 | 11 km |
| 07/2022 | 21,338 km |
| 11/2024 | 43,936 km |

Legal status
Has the vehicle passed technical inspection? Was it marked as scrapped?

No issues found
No records about the legal status of this vehicle were found

Legal


 **Technical inspection (MOT)** **Passed** 11/2024  Poland Has successfully passed technical inspection

 **Scrap** ✓ No record found No record that vehicle was marked as scrapped

Damage
This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

No issues found

Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters
Has the vehicle's location been recorded in the area of a natural disaster?

No issues found
Vehicle's location was not recorded in the area of a natural disaster

Market value
How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

Note

- Average market price for such vehicle: €19,506
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!


Renault Master 2020 market value today
Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price
€16,924

Average price
€19,506

Highest price
€62,956

Emissions
How much CO2 emissions do vehicles of this model/year produce?

 **carVertical Insight**
This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

CO₂ emissions
Emission CO₂ g/km
Your vehicle CO₂ emissions: **6 g/km** Class **A**

Up to 120

120 - 140

140 - 155

155 - 165

165 - 190


190 - 225


225 +


Specs & equipment
What specs and equipment are on record for this vehicle?


Note
Check whether the specs and equipment of this vehicle match the facts given by the seller.


Identification and technical specifications


 **Make**
Renault


 **Model**
Master


 **Description**
Master


 **Body type**
Van


 **Manufacture year**
2020


 **Powertrain displacement**
2.3 L


 **Powertrain power**
99 kW (133 hp)


 **Fuel type**
Diesel


 **Transmission type**
Manual

 **Drive type**
FWD

 **Number of gears**
6

 **Gross weight**
3,500 kg

 **Curb weight**
1,974 kg

 **CO2 emissions**
6 g/km

Equipment
As received from the manufacturer

2ND ROW SEATS
WITHOUT (OP2RAN)

ADDITIONAL FLOOR
WITHOUT FLOOR ADDITIVE (SSADPL)

ADDITIONAL KEY
WITHOUT ADDITIONAL KEY (SCLSUP)

ADJUSTMENT OF FRONT SEAT BELTS
HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)

ANTI-THEFT DEVICES
WITHOUT ANTI-THEFT DEVICE (SDPCLV)

BLIND SPOT DETECTION
WITHOUT DETECTOR BLIND S (SDANGM)

CERTIFICATION EVOLUTION
COMPLEMENTARY OBJECT (NOH12)

ACCESSORY SOCKET
WITHOUT ACCESSORY SOCKET (SSPACC)

ADDITIONAL HEADLIGHTS
FOG LIGHTS (PROJAB)

ADDITIONAL LOCK
CONTEXT CRITERIOM (SANA89)

AIRBAG CANCEL
DECONNEX AIRBAG PASS (AIRBDE)

BATTERY POWER TRACTION
WITHOUT BATTERY ENERGY (SSCABA)

BRAKING ASSISTANCE
BOOSTER EMERGENCY BRAKING (AFURGE)

CKD GROUPING ZONE
COMPLEMENTARY OBJECT (NO031)

COMMERCIAL VERSION SUPPLEMENT
BASIC COMMERCIAL VERSION (VNOR)

COUNTER UNIT
KILOMETRES (KM)

DAYTIME RUNNING LIGHTS
DAYTIME RUNNING LIGHTS 2 (FDIU2)

DOUBLE TIRE
WITHOUT WHEEL COUPLED (SROUJU)

DRIVER'S HANDBOOK
ITALIAN GLOVE BOX LITERAT (NOTITA)

ECONOMIC DRIVING
WITH ECO MODE (ECOMOD)

ELECTRIC VEHICLE BATTERY CHARGING
COMPLEMENTARY OBJECT (SAN269)

ELECTRONIC STABILITY PROGRAM
DIRECTIONAL STABILITY CON (ASRESP)

ENGINE PRODUCTION PLANT
(C) PLANT PROD (APV002_C)

EXT MIRROR PROJECTION
EXTERIOR REAR VIEW MIRROR (RPETIT)

FAST TRACK
COMPLEMENTARY OBJECT (NOH70)

FORWARD EMERGENCY BRAKING
WITHOUT URB ADV EM BRAKE (SSAEB5)

FRONT ARM REST
WITH FRONT ARMREST (ACCAV)

FRONT SEAT SUITABLE FOR CHILDREN
NON-ISOFIX SEAT (SSISOF)

FRONT TYRES
225/65 R16 C(112/110)T, 6.50 J 16 - 66 C2 A

GEARBOX PRODUCTION PLANT
(C) CLEON (FRANCE) (APV003_C)

GLOVE BOX
GLOVE BOX 2 (BTAGA2)

HORN
CONTEXT CRITERIOM (SANA39)

INSTRUMENT PANELS

CONDITIONING
STANDARD PROTECTION (CONDO)

COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION
TECHNICAL REG: ITALY (TLITAL)

DOOR OPENING REMOTE CONTROL TYPE
315 MHZ NORMAL DOOR OPENI (SOP02B)

DRIVER SEAT TYPE
DRIVER SEAT WITH LUMBAR A (COLOMB)

DUST PROTECTION
WITHOUT DUST KIT (SKTPOU)

ELECTRIC TOLL COLLECTION
WO ELECTRONIC TOLL SYS SP (SSPTLP)

ELECTROMOTOR DOOR LOCKING
ELECTRIC DOOR LOCKING (CPE)

EMERGENCY CALL AND BREAKDOWN
WITHOUT CALL FONCTION (SSCALL)

ENTRY GRIP
CONTEXT CRITERIOM (SANC32)

EXTERIOR REAR VIEW MIRRORS
2 ELEC OUTSIDE MIRRORS (RETROE)

FIRE EXTINGUISHER
WITHOUT EQUIPMENT LEVEL O (SPREXT)

FRONT AND REAR PROXIMITY RADAR
PROXIMITY RADAR (RDPROX)

FRONT PASSENGER SEAT ADJUSTMENT
MULTI-FUNCTION PASSENGER BENCH SEAT TYPE 3 (BOBUR3)

FRONT SIDE AIRBAG
WITHOUT FRONT SIDE AIRBAG (SABLAV)

GEAR SHIFT INDICATOR
WITH GEAR SHIFT INDICATOR (AVGSI)

GEOGRAPHIC COUNTRY
COMPLEMENTARY OBJECT (SAN328)

HARNES MODULAR MANAGEMENT1
MODULAR MANAGEMENT A 641 (GMA641)

IN USE PERFORMANCE RATING
WITH IN USE PERFORMANCE R (AUIUPR)

INTELLECTUAL PROPERTY

INSTRUMENT PANEL O6 (TBOR06)
INTERIOR CARGO SIDE TRIM
WITHOUT INTERIOR SIDE LIN (SSHLIN)

INTERIOR REAR VIEW MIRROR
COMPLEMENTARY OBJECT (SAN298)

INVARIANT PROCESS SHEET MODEL
MODEL ROUTING SHEET (X622UV)

LANE KEEP
W/O LANE DEPARTURE WARNI (SLDLMG)

LIGHT PROTECTION
CONTEXT CRITERIOM (SANE16)

LUGGAGE COVER
COMPLEMENTARY OBJECT (SAN106)

MAKE OF TYRES
TYRE BRAND: UNMARKED FITT (BANAL)

MISCELLANEOUS BENEFITS : MASSES
CONTEXT CRITERIOM (SAND70)

MISCELLANEOUS DIX
WITHOUT PRESTATION (SPRDIX)

MUD FLAP
MUD-GUARDS WITHOUT FLAPS (SSBAV)

NAVIGATION/SMARTPHONE IMITATION
COMPLEMENTARY OBJECT (NOG72)

OPTIONAL FRONT TYRES
225/65 R16 C(112/110)T, 6.50 J 16 - 66

PARKING BRAKE TYPE
WITHOUT AUTOMATIC PARKING (SSFRPA)

PASSENGER COMPARTMENT HEATING TYPE
AIR-CONDITIONING (CA)

PLANT ASSEMBLY LINE
ASSEMBLY LINE 1 (CHMON1)

POLLEN/DUST FILTER
WITH POLLEN FILTER (FIPOU)

PRESTATION EIGHT
COMPLEMENTARY OBJECT (SANE44)

RADIO COVER
COMPLEMENTARY OBJECT (NO351)

CONTEXT CRITERIOM (SAN114)
INTERIOR COLOUR STYLING
INTERIOR HARMONY 01 (HARM01)

INTERIOR ROOF TRIM
WITHOUT ROOF TRIM STYLE (SHABPV)

LADDER
COMPLEMENTARY OBJECT (SAND82)

LEVEL OF NAVIGATION AID
WITHOUT NAVIGATION AID (SSNAV)

LUGGAGE BOX
W/O LUGGAGE BOX (SRANCF)

LUGGAGE RACK
COMPLEMENTARY OBJECT (SAN107)

MARKETING VERSION
COMMERCIAL VERSION (VEC155)

MISCELLANEOUS BENEFITS SIXT
COMPLEMENTARY OBJECT (SANE26)

MODE 2 CABLE
COMPLEMENTARY OBJECT (SANE60)

NAVIGATION MAP
STANDARD MAPPING (MAPSTD)

ON-BOARD WARRANTY/SERVICES
SERVICES BOOKLET (RSANA1)

OPTIONAL REAR TYRES
225/65 R16 C(112/110)T, 6.50 J 16 - 66

PARTITION INSULATION
WITHOUT PARTITION TRIM (SHABCL)

PASSENGER COMPARTMENT THERMAL REQUIREMENT 1 (THABT1)
PASSENGER COMPARTMENT THERMAL REQUIREMENT 1 (THABT1)

PLANT MARKING FOR COMPLEX START
COMPLEMENTARY OBJECT (SANS87)

POWER STEERING
COMPLEMENTARY OBJECT (SAND44)

PROTECTION ELEMENTS
DR AIRBAG (AIRBA1)

REAR BOX
CONTEXT CRITERIOM (SANS35)

REAR CARPET - FLOOR
CONTEXT CRITERIOM (SAN199)

REAR DIFFERENTIAL LOCK
WITHOUT REAR DIFF LOCK (SBLARR)

REAR SCREEN BLIND
WITHOUT BLIND (SSRIDO)

REAR STEP BOARD
WITHOUT REAR SIDE SILL (SMPDAR)

REAR WINDOW
NON-HEATED REAR SCREEN (LNC)

ROOF RACK/BARS
COMPLEMENTARY OBJECT (SANO43)

SEAT BELT REMINDER
W S BEALT NOT SECURE DRIV (ALOUCC)

SEAT HEATER AND COOLER
NON-HEATED SEAT (SGSCHHA)

SEAT TRIMS
VELVET CLOTH (DRA)

SERVICE AHA
COMPLEMENTARY OBJECT (SANG16)

SERVICE DONGLE
COMPLEMENTARY OBJECT (NOH14)

SHELF OF PANEL INSTRUMENT
WO SHELF PANEL INSTRUM (STABPB)

SMOKER'S ACCESSORIES
WITHOUT SMOKER ACCESSORIE (SANACF)

SPECIAL BUILD (FACTORY)
SERIES VEHICLE (WITHOUT S (SERIE)

STAND FOR TABLE COMPUTER
WITHOUT STAND FOR TABLE (SSUTAB)

STEERING WHEEL POSITION
LEFT (DG)

STRIPPING
COMPLEMENTARY OBJECT (SAN224)

SUPPLEMENTARY CONVERSION
WITHOUT SUPPLEMENTARY CONVERSION (SANADP)

TECHNICAL EVOLUTION A
COMPLEMENTARY OBJECT (NOG66)

REAR CONNECTION DEVICE
WO ADAPTATION CONNECTION (SADPCN)

REAR EXTENDED WIRING
WITHOUT WIRING LENGTHENS (SCABAL)

REAR SEATS ADDITIONAL HEATING
WITHOUT REAR SEAT HEATING (SCHAD)

REAR TYRES
225/65 R16 C(112/110)T, 6.50 J 16 - 66 C2 A

ROAD SEVERITY
TYPE OF ROAD STANDARD (TRNOR)

ROUTING SHEETS COUNTRY
ITALY (ITAL)

SEAT COVERS
FABRIC SEAT-LINING N 01 (DRAP01)

SEAT REMOVABLE
SEAT NOT REMOVABLE (SGNAMO)

SEATS: 3RD ROW
0 SEAT - THIRD ROW SEATS (OP3RAN)

SEATING COUNTRY
COMPLEMENTARY OBJECT (SANS47)

SERVICE TMC
WITHOUT SERVICE TMC (SSRTMC)

SIDE STEP BOARD
COMPLEMENTARY OBJECT (SAN283)

SPARE WHEEL
WITH A SPARE WHEEL (RSEC01)

SPEED LIMITER
WITHOUT SPEED LIMITER (SSLVIT)

STARTUP CRITERIA
COMPLEMENTARY OBJECT (SANS8W)

STORAGE FOR ACCESSORIES
CONTEXT CRITERIOM (SANA49)

SUPPLEMENTARY CHILD PACK
WITHOUT CHILD PACK SUPPLE (SCPKEF)

TACHOGRAPH
WITHOUT TACHOGRAPH (SANCTL)

TECHNICAL EVOLUTION N
COMPLEMENTARY OBJECT (NOH56)

TOW HOOK
CONTEXT CRITERIOM (SAN260)

TRACTION BATTERY CONTRACT
CONTEXT CRITERIOM (SANE04)

TYPE OF CUMPER / TRAY
WITHOUT DUMP BODY (SSBENN)

TYPE OF HEADLIGHTS
HEADLIGHT 01 (PROJ1)

TYPE OF REFRIGERANT GAS
GAS TYPE R134A (R134A)

TYPES OF RADIOS
RAD ENTRY DAB 4HP (RA420)

UNDERBODY PROTECTION
WO ANTIGRIT PROTECTION (SKTGRV)

UPPER DASHBOARD STORAGE
WO DASHBOARD STORAGE (SRGPDB)

UTILITY ADAPTATION COVER SPECIFI
COMPLEMENTARY OBJECT (NOH64)

VARIOUS ADDITIONAL FEATURES
COMPLEMENTARY OBJECT (SANA482)

VEHICLE HEIGHT LEVEL ADJUSTER
NON-PNEUMATIC SUSPENSION (SUSPNPN)

VEHICLE PRODUCTION PLANT
(B) PLANT PROD (APV001_B)

VEHICLE TRANSFORMATION
WO VEHICLE TRANSFORMATIO (SSTREVF)

WHEEL DISC PROTECTION
WITHOUT PROTECTIVE REAR B (SPRODI)

WHEEL TRIM
HUBCAP 01 (ENJ001)

WIDE ANGLE REAR VIEW
WITH BUS REAR VIEW MIR 2 (RTVIO2)

WIPER START-UP TYPE
AUTOMATIC LIGHTS + WINDSCREEN WIPER (ALEVA)

WIRING FOR CONVERSION
WITHOUT WIRING ADAP. (SCBADP)

TRACK WIDTH
CONTEXT CRITERIOM (SAND62)

TYPE OF CLIMATE
TEMPERATE CLIMATE (TEMP)

TYPE OF FRONT WINDSHIELD WINDER
DRIVER: MOTOR UNIT / PASSENGER: MOTOR UNIT (LVAEL)

TYPE OF PARTITION
FULL METAL BULKHEAD (CLCTOL)

TYPE OF TYRES
STANDARD TYRE (PNSTRD)

TYRE PRESSURE DETECTION
WITHOUT TYRE PRESSURE DET (SDPRPN)

UNIVERSAL INTERCONNECT FUNCTION
WITHOUT TCU (SSTCU)

UTILITY ADAPTATION COVER
WITHOUT ADAPTATION (SANA164)

UTILITY ADAPTATION INTEG PART1
CONTEXT CRITERIOM (SANS650)

VARIOUS FUNCTIONS
COMPLEMENTARY OBJECT (SANT270)

VEHICLE LIGHT CONVERSION
WO LIGHT ADAPTATION SVO (SANCML)

VEHICLE TRACKING SYSTEM
W/O SECURITY DEVICE (SDPSEC)

WATER PROTECTION
WO RAIN FORD RIVER KIT (SKTPGR)

WHEEL RIM TYPE
16 METAL WHEEL RIMS 1 (RTOL16)

WHEELS RIMS
COMPLEMENTARY OBJECT (SANA497)

WINDOW TINT
TINTED WINDOWS (VT)


WIRELESS PHONE CHARGE
WO TELEPHONY ACCES REFI (SREACT)


Timeline
7 records found

The timeline of records for this vehicle


Records


12/2020

 **Country unknown**


 **Was manufactured**
The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.


03/2021

 **Italy**


 **First registration**
The record represents an administrative event. This could be related to a change of ownership, documents, etc


10/2024

 **Italy**


 **Was on sale**
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.


10/2024

 **Italy**


 **Was deregistered**
The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.


11/2024

 **Poland**


 **Was inspected**
A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.


11/2024


 **Country unknown**

 **Was insured**
The vehicle was insured in this country (or state). The record may refer to all kinds of insurance (third-party liability, KASKO, etc.) and reinsurance events.
From: 11/21/2024 To: 12/20/2024

11/2024

 **Poland**

 **Was registered**
The record represents an administrative event. This could be related to a change of ownership, documents, etc

 **Data sources**
We checked 900+ data sources in **35 countries**