

DS

VIN: VR1JCYHZUMY531712

Generated on 05/20/2025, 05:54 PM

Scan for full report

Purpose

✓ Looks good

Odometer

✓ Looks good

Legal status

✓ Looks good

Damage

✓ Looks good

+31 **Data sources**
We checked 900+ data sources in **35 countries**

Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

✓

No issues found

No records of vehicle being used in irregular manner

Here's what we checked:

- Taxi

✓ No record found

No evidence of being used as a taxi
- Transport

✓ No record found

No evidence of being used as a transport vehicle
- Rental

✓ No record found

No evidence of being used as a rental vehicle
- Police

✓ No record found

No evidence of being used by police
- Demo

✓ No record found

No evidence of being used as a demo vehicle
- Driving school vehicle

✓ No record found

No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

✓

No issues found

We didn't find any records that the vehicle was stolen.

Note

Police database stolen vehicle check completed in **11 countries**: +5

Here's what we checked:

- Currently wanted as stolen

✓ No record found
- Stolen in the past

✓ No record found

No past theft records found for this vehicle.

Police database stolen vehicle **check completed in**:


- United States
- Sweden
- Denmark
- Canada
- Lithuania
- Slovenia
- Romania
- Hungary
- Slovakia
- Italy
- Czechia

Odometer

Are there signs of mileage rollbacks or discrepancies?

Note

- Last known mileage: 11 km
- 1 mileage record found



Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

✓

No issues found

No records about the legal status of this vehicle were found

Legal

- Technical inspection (MOT)

✓ No record found

No technical inspection records found
- Scrap

✓ No record found

No record that vehicle was marked as scrapped


Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

✓

No issues found

Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

✓

No issues found

Vehicle's location was not recorded in the area of a natural disaster

Specs

What specs and equipment are on record for this vehicle?

Note

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

- Make

DS
- Powertrain displacement

1.5 L
- Powertrain power

96 kW (129 hp)
- Number of seats

5

Timeline

2 records found

- The timeline of records for this vehicle
- Records
- 10/2021 Italy

First registration

The record represents an administrative event. This could be related to a change of ownership, documents, etc
- 01/2025 Italy

Was deregistered

The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.

+31 **Data sources**
We checked 900+ data sources in **35 countries**