CARVERTICAL

Renault Master

VIN: VF1MA000668391811 | Diesel | 2021

Generated on 06/09/2025

Scan for full report

Purpose ✓ Looks good | Mileage ✓ Looks good | Legal status ✓ Looks good | Damage ✓ Looks good

+36 **Data sources** We checked 900+ data sources in **40 countries**

Photos

We found **81** photos of this vehicle. Scan report QR code to see all.

09/2024



Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

✓ **No issues found**
No records of vehicle being used in irregular manner

Here's what we checked:

Taxi ✓ No record found No evidence of being used as a taxi
Transport ✓ No record found No evidence of being used as a transport vehicle
Rental ✓ No record found No evidence of being used as a rental vehicle
Police ✓ No record found No evidence of being used by police
Demo ✓ No record found No evidence of being used as a demo vehicle
Driving school vehicle ✓ No record found No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

✓ **No issues found**
We didn't find any records that the vehicle was stolen.

Note
Police database stolen vehicle check completed in **11 countries:** +5

Here's what we checked:

Currently wanted as stolen ✓ No record found
Stolen in the past ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle **check completed in:**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Slovenia | Czechia | Romania | Slovakia | Hungary | Italy | Canada | United States | Lithuania | Denmark | Sweden

Mileage

Are there signs of mileage rollbacks or discrepancies?

Note
- Last known mileage: 135,211 km
- Average mileage for similar models: 105,964 km
- 4 mileage records found



Odometer records

12/2021	11 km
09/2023	85,113 km
09/2024	135,196 km
10/2024	135,211 km

Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

✓ **No issues found**
No records about the legal status of this vehicle were found

Legal

Technical inspection (MOT) Passed 10/2024 Poland Has successfully passed technical inspection
Scrap ✓ No record found No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

✓ **No issues found**

Damage records

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

✓ **No issues found**
Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

Note
- Average market price for such vehicle: €20,863
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Renault Master 2021 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price	Average price	Highest price
€18,206	€20,863	€23,779

Emissions

How much CO2 emissions do vehicles of this model/year produce?

carVertical Insight
This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

CO_2 emissions

Emission CO_2 g/km



Specs & equipment

What specs and equipment are on record for this vehicle?

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Note
Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

Make	**Renault**
Model	**Master**
Description	**Master**
Body type	**Van**
Manufacture year	**2021**
Powertrain displacement	**2.3 L**
Powertrain power	**99 kW (133 hp)**
Fuel type	**Diesel**
Transmission type	**Manual**
Drive type	**FWD**
Number of gears	**6**
Gross weight	**3,500 kg**
Curb weight	**2,069 kg**
CO2 emissions	**6 g/km**

Equipment

As received from the manufacturer

2ND ROW SEATS	WITHOUT (0P2RAN)
ADDITIONAL FLOOR	WITHOUT FLOOR ADDITIVE (SSADPL)
ADDITIONAL KEY	WITHOUT ADDITIONAL KEY (SCLSUP)
ADJUSTMENT OF FRONT SEAT BELTS	HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)
ANTI-THEFT DEVICES	WITHOUT ANTI-THEFT DEVICE (SDPCLV)
BLIND SPOT DETECTION	WITHOUT DECTECTOR BLIND S (SDANGM)
CERTIFICATION EVOLUTION	COMPLEMENTARY OBJECT (NOH12)
COMMERCIAL VERSION SUPPLEMENT	BASIC COMMERCIAL VERSION (VNOR)
ACCESSORY SOCKET	WITHOUT ACCESSORY SOCKET (SSPACC)
ADDITIONAL HEADLIGHTS	WITHOUT ADDITIONAL HEADLIGHT (SPROJA)
ADDITIONAL LOCK	CONTEXT CRITERIOM (SANA89)
AIRBAG CANCEL	DECONNEX AIRBAG PASS (AIRBDE)
BATTERY POWER TRACTION	WITHOUT BATTERY ENERGY (SSCABA)
BRAKING ASSISTANCE	BOOSTER EMERGENCY BRAKING (AFURGE)
CKD GROUPING ZONE	COMPLEMENTARY OBJECT (NO031)
CONDITIONING	STANDARD PROTECTION (COND0)

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

COUNTER UNIT	KILOMETRES (KM)
DAYTIME RUNNING LIGHTS	DAYTIME RUNNING LIGHTS 2 (FDIU2)
DOUBLE TIRE	WITHOUT WHEEL COUPLED (SROUJU)
DRIVER'S HANDBOOK	ITALIAN GLOVE BOX LITERAT (NOTITA)
ECONOMIC DRIVING	WITH ECO MODE (ECOMOD)
ELECTRIC VEHICLE BATTERY CHARGING	COMPLEMENTARY OBJECT (SAN269)
ELECTRONIC STABILITY PROGRAM	DIRECTIONAL STABILITY CON (ASRESP)
ENGINE PRODUCTION PLANT	(C) PLANT PROD (APV002_C)
EXT MIRROR PROJECTION	EXTERIOR REAR VIEW MIRROR (RPETIT)
FAST TRACK	COMPLEMENTARY OBJECT (NOH70)
FORWARD EMERGENCY BRAKING	WITHOUT URB ADV EM BRAKE (SSAEBS)
FRONT ARM REST	WITH FRONT ARMREST (ACCAV)
FRONT SEAT SUITABLE FOR CHILDREN	NON-ISOFIX SEAT (SSISOF)
FRONT TYRES	225/65 R16 C(112/110)T, 6.50 J 16 - 66 C2 A
GEARBOX PRODUCTION PLANT	(C) CLEON (FRANCE) (APV003_C)
GLOVE BOX	GLOVE BOX 2 (BTAGA2)
HORN	CONTEXT CRITERIOM (SANA39)
INSTRUMENT PANELS	INSTRUMENT PANEL 06 (TBOR06)
INTERIOR CARGO SIDE TRIM	WITHOUT INTERIOR SIDE LIN (SSHLIN)
INTERIOR REAR VIEW MIRROR	COMPLEMENTARY OBJECT (SAN298)
INVARIANT PROCESS SHEET MODEL	MODEL ROUTING SHEET (X622UV)
LANE KEEP	W/O LANE DEPARTURE WARNI (SDLIGM)
LIGHT PROTECTION	CONTEXT CRITERIOM (SANE16)
LUGGAGE COVER	COMPLEMENTARY OBJECT (SAN106)
MAKE OF TYRES	TYRE BRAND: UNMARKED FITT (BANAL)
MISCELLANEOUS BENEFITS : MASSES	CONTEXT CRITERIOM (SAND70)
MISCELLANEOUS DIX	WITHOUT PRESTATION (SPRDIX)
COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION	TECHNICAL REG: ITALY (TLITAL)
DOOR OPENING REMOTE CONTROL TYPE	315 MHZ NORMAL DOOR OPENI (SOP02B)
DRIVER SEAT TYPE	DRIVER SEAT WITH LUMBAR A (COLOMB)
DUST PROTECTION	WITHOUT DUST KIT (SKTPOU)
ELECTRIC TOLL COLLECTION	WO ELECTRONIC TOLL SYS SP (SSPTLP)
ELECTROMOTOR DOOR LOCKING	ELECTRIC DOOR LOCKING (CPE)
EMERGENCY CALL AND BREAKDOWN	WITHOUT CALL FONCTION (SSCALL)
ENTRY GRIP	CONTEXT CRITERIOM (SANC32)
EXTERIOR REAR VIEW MIRRORS	2 ELEC OUTSIDE MIRRORS (RETROE)
FIRE EXTINGUISHER	WITHOUT EQUIPMENT LEVEL O (SPREXT)
FRONT AND REAR PROXIMITY RADAR	PROXIMITY RADAR TYPE 05 (RDAR05)
FRONT PASSENGER SEAT ADJUSTMENT	MULTI-FUNCTION PASSENGER BENCH SEAT TYPE 3 (BQBUR3)
FRONT SIDE AIRBAG	WITHOUT FRONT SIDE AIRBAG (SABLAV)
GEAR SHIFT INDICATOR	WITH GEAR SHIFT INDICATOR (AVGSI)
GEOGRAPHIC COUNTRY	COMPLEMENTARY OBJECT (SAN328)
HARNESS MODULAR MANAGEMENT	MODULAR MANAGEMENT A 691 (GMA691)
IN USE PERFORMANCE RATING	WITH IN USE PERFORMANCE R (AVIUPR)
INTELLECTUAL PROPERTY	CONTEXT CRITERIOM (SAN114)
INTERIOR COLOUR STYLING	INTERIOR HARMONY 01 (HARM01)
INTERIOR ROOF TRIM	WITHOUT ROOF TRIM STYLE (SHABPV)
LADDER	COMPLEMENTARY OBJECT (SAND82)
LEVEL OF NAVIGATION AID	WITHOUT NAVIGATION AID (SSNAV)
LUGGAGE BOX	W/O LUGGAGE BOX (SRANCF)
LUGGAGE RACK	COMPLEMENTARY OBJECT (SAN107)
MARKETING VERSION	COMMERCIAL VERSION (VEC158)
MISCELLANEOUS BENEFITS SIXT	COMPLEMENTARY OBJECT (SANE26)
MODE 2 CABLE	COMPLEMENTARY OBJECT (SANE60)

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

MUD FLAP	MUD-GUARDS WITHOUT FLAPS (SSBAV)
NAVIGATION/SMARTPHONE IMITATION	COMPLEMENTARY OBJECT (NOG72)
OPTIONAL FRONT TYRES	225/65 R16 C(112/110)T, 6.50 J 16 - 66
PARKING BRAKE TYPE	WITHOUT AUTOMATIC PARKING (SSFRPA)
PASSENGER COMPARTMENT HEATING TYPE	AIR-CONDITIONING (CA)
PLANT ASSEMBLY LINE	ASSEMBLY LINE 1 (CHMON1)
POLLEN/DUST FILTER	WITH POLLEN FILTER (FIPOU)
PRESTATION EIGHT	COMPLEMENTARY OBJECT (SANE44)
RADIO COVER	COMPLEMENTARY OBJECT (NO351)
REAR CARPET - FLOOR	CONTEXT CRITERIOM (SAN199)
REAR DIFFERENTIAL LOCK	WITHOUT REAR DIFF LOCK (SBLARR)
REAR SCREEN BLIND	WITHOUT BLIND (SSRIDO)
REAR STEP BOARD	WITHOUT REAR SIDE SILL (SMPDAR)
REAR WINDOW	NON-HEATED REAR SCREEN (LNC)
ROOF RACK/BARS	COMPLEMENTARY OBJECT (SAN043)
SEAT BELT REMINDER	SEAT BELT WARN TYPE 5 (ALOUC5)
SEAT HEATER AND COOLER	NON-HEATED SEAT (SGSCHA)
SEAT TRIMS	VELVET CLOTH (DRA)
SERVICE AHA	COMPLEMENTARY OBJECT (SANG16)
SERVICE DONGLE	COMPLEMENTARY OBJECT (NOH14)
SHELF OF PANEL INSTRUMENT	WO SHELF PANEL INSTRUM (STABPB)
SMOKER'S ACCESSORIES	WITHOUT SMOKER ACCESSORIE (SANACF)
SPECIAL BUILD (FACTORY)	SERIES VEHICLE (WITHOUT S (SERIE)
STAND FOR TABLET COMPUTER	WITHOUT STAND FOR TABLET (SSUTAB)
STEERING WHEEL POSITION	LEFT (DG)
STRIPPING	COMPLEMENTARY OBJECT (SAN224)
NAVIGATION MAP	STANDARD MAPPING (MAPSTD)
ON-BOARD WARRANTY/SERVICES	SERVICES BOOKLET (RSANA1)
OPTIONAL REAR TYRES	225/65 R16 C(112/110)T, 6.50 J 16 - 66
PARTITION INSULATION	WIHTOUT PARTITION TRIM (SHABCL)
PASSENGER COMPARTMENT THERMAL REQUIREMENT	WITHOUT PASSENGER COMPARTMENT THERMAL REQUIREMENT (STHABT)
PLANT MARKING FOR COMPLEX START	COMPLEMENTARY OBJECT (SAN587)
POWER STEERING	COMPLEMENTARY OBJECT (SAND44)
PROTECTION ELEMENTS	DR AIRBAG (AIRBA1)
REAR BOX	CONTEXT CRITERIOM (SAN535)
REAR CONNECTION DEVICE	WO ADAPTATION CONNECTION (SADPCN)
REAR EXTENDED WIRING	WHITHOUT WIRING LENGTHENS (SCABAL)
REAR SEATS ADDITIONAL HEATING	WITHOUT REAR SEAT HEATING (SCHAD)
REAR TYRES	225/65 R16 C(112/110)T, 6.50 J 16 - 66 C2 A
ROAD SEVERITY	TYPE OF ROAD STANDARD (TRNOR)
ROUTING SHEETS COUNTRY	ITALY (ITAL)
SEAT COVERS	FABRIC SEAT-LINING N 01 (DRAP01)
SEAT REMOVABLE	SEAT NOT REMOVABLE (SGNAMO)
SEATS: 3RD ROW	0 SEAT - THIRD ROW SEATS (0P3RAN)
SERVICE COUNTRY	COMPLEMENTARY OBJECT (SAN547)
SERVICE TMC	WITHOUT SERVICE TMC (SSRTMC)
SIDE STEP BOARD	COMPLEMENTARY OBJECT (SAN283)
SPARE WHEEL	REPAIR INFLATION KIT (KTGREP)
SPEED LIMITER	WITHOUT SPEED LIMITER (SSLVIT)
STARTUP CRITERIA	COMPLEMENTARY OBJECT (SAN58W)
STORAGE FOR ACCESSORIES	CONTEXT CRITERIOM (SANA49)
SUPPLEMENTARY CHILD PACK	WITHOUT CHILD PACK SUPPLE (SCPKEF)

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

SUPPLEMENTARY CONVERSION	WITHOUT SUPPLEMENTARY CONVERSION (SANADP)
TECHNICAL EVOLUTION A	COMPLEMENTARY OBJECT (NOG66)
TOW HOOK	CONTEXT CRITERIOM (SAN260)
TRACTION BATTERY CONTRACT	CONTEXT CRITERIOM (SANE04)
TYPE OF DUMPER / TRAY	WITHOUT DUMP BODY (SSBENN)
TYPE OF HEADLIGHTS	HEADLIGHT 01 (PROJ1)
TYPE OF REFRIGERANT GAS	GAS TYPE R134A (R134A)
TYPES OF RADIOS	RAD ENTRY DAB 4HP (RA420)
UNDERBODY PROTECTION	WO ANTIGRIT PROTECTION (SKTGRV)
UPPER DASHBOARD STORAGE	WO DASHBOARD STORAGE (SRGPDB)
UTILITY ADAPTATION COVER SPECIFI	COMPLEMENTARY OBJECT (NOH64)
VARIOUS ADDITIONAL FEATURES	COMPLEMENTARY OBJECT (SAN482)
VEHICLE HEIGHT LEVEL ADJUSTER	NON-PNEUMATIC SUSPENSION (SUSNPN)
VEHICLE PRODUCTION PLANT	(B) PLANT PROD (APV001_B)
VEHICULE TRANSFORMATION	WO VEHICULE TRANSFORMATIO (SSTRFV)
WHEEL DISC PROTECTION	WITHOUT PROTECTIVE REAR B (SPRODI)
WHEEL TRIM	HUBCAP 01 (ENJO01)
WIDE ANGLE REAR VIEW	WITHOUT BUS REAR VIEW MIR (SSRETV)
WIPER START-UP TYPE	AUTOMATIC LIGHTS + WINDSCREEN WIPER (ALEVA)
WIRING FOR CONVERSION	WITHOUT WIRING ADAP. (SCBADP)
TACHOGRAPH	WITHOUT TACHOGRAPH (SANCTL)
TECHNICAL EVOLUTION N	COMPLEMENTARY OBJECT (NOH56)
TRACK WIDTH	CONTEXT CRITERIOM (SAND62)
TYPE OF CLIMATE	TEMPERATE CLIMATE (TEMP)
TYPE OF FRONT WINDOW WINDER	DRIVER: MOTOR UNIT / PASSENGER: MOTOR UNIT (LVAVEL)
TYPE OF PARTITION	FULL METAL BULKHEAD (CLCTOL)
TYPE OF TIRES	STANDARD TYRE (PNSTRD)
TYRE PRESSURE DETECTION	WITHOUT TYRE PRESSURE DET (SDPRPN)
UNIVERSAL INTERCONNECT FUNCTION	WITHOUT TCU (SSTCU)
UTILITY ADAPTATION COVER	WITHOUT ADAPTATION (SAN164)
UTILITY ADAPTATION INTEG PARTI+	CONTEXT CRITERIOM (SAN650)
VARIOUS FUNCTIONS	COMPLEMENTARY OBJECT (SAN270)
VEHICLE LIGHT CONVERSION	WO LIGHT ADAPTATION SVO (SANCML)
VEHICLE TRACKING SYSTEM	W/O SECURITY DEVICE (SDPSEC)
WATER PROTECTION	WO RAIN FORD RIVER KIT (SKTPGR)
WHEEL RIM TYPE	16 METAL WHEEL RIMS 1 (RTOL16)
WHEELS RIMS	COMPLEMENTARY OBJECT (SAN497)
WINDOW TINT	TINTED WINDOWS (VT)
WIRELESS PHONE CHARGE	WO TELEPHONY ACCES REFIL (SREACT)

Timeline

7 records found

The timeline of records for this vehicle

Records

12/2021 Country unknown
Was manufactured
The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

01/2022 Italy
First registration
The record represents an administrative event. This could be related to a change of ownership, documents, etc

09/2024 Italy
Was on sale
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

09/2024 Italy
Was deregistered
The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.

10/2024 Poland
Was inspected
A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

10/2024 Poland
Was insured
The vehicle was insured in this country (or state). The record may refer to all kinds of insurance (third-party liability, KASKO, etc.) and reinsurance events.
From: **10/23/2024** To: **11/21/2024**

10/2024 Poland
Was registered
The record represents an administrative event. This could be related to a change of ownership, documents, etc

+36 **Data sources** We checked 900+ data sources in **40 countries**

This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.