


BMW 318

VIN: WBA6L31060FJ52599


Diesel

2020

Generated on 05/20/2025, 05:55 PM




Scan for full report




**Purpose**

✓ Looks good




**Odometer**

✓ Looks good




**Legal status**

✓ Looks good



**Damage**

⚠ Needs attention

 +31 **Data sources**  
We checked 900+ data sources in 35 countries

## Photos

We found 41 photos of this vehicle. Scan report QR code to see all.


05/2023


## Purpose


Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!


✓ **No issues found**  
No records of vehicle being used in irregular manner


Here's what we checked:


 **Taxi** ✓ No record found No evidence of being used as a taxi

 **Transport** ✓ No record found No evidence of being used as a transport vehicle

 **Rental** ✓ No record found No evidence of being used as a rental vehicle

 **Police** ✓ No record found No evidence of being used by police



 **Demo** ✓ No record found No evidence of being used as a demo vehicle

 **Driving school vehicle** ✓ No record found No evidence of being used as a driving school vehicle


## Theft


Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

✓ **No issues found**  
We didn't find any records that the vehicle was stolen.




 **Note**  
Police database stolen vehicle check completed in 6 countries: 




Here's what we checked:

 **Currently wanted as stolen** ✓ No record found

 **Stolen in the past** ✓ No record found No past theft records found for this vehicle.


Police database stolen vehicle **check completed in:**

 **Italy**  **Canada**  **Denmark**


 **United States**  **Lithuania**  **Sweden**

## Odometer

Are there signs of mileage rollbacks or discrepancies?

 **Note**

- Last known mileage: 151,996 km
- Average mileage for similar models: 104,907 km
- 6 mileage records found

 **carVertical Insight**  
It seems this vehicle wasn't being used for a while. There may be a good reason, but it's still useful to learn the facts. Was it damaged? Was there an expensive issue (engine / transmission failure, etc.)? Was there a mileage rollback?

Odometer records	
02/2020	16 km
03/2021	54,500 km
11/2021	95,000 km
03/2022	106,000 km
05/2023	151,985 km

Odometer records	
12/2024	151,996 km


## Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

✓ **No issues found**  
No records about the legal status of this vehicle were found

Legal


✓ = **Technical inspection (MOT)** ✓ No record found No technical inspection records found

 **Scrap** ✓ No record found No record that vehicle was marked as scrapped


## Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).


⚠ **Beware**  
We found 3 records for this vehicle

 **Note**  
Mild damages normally won't impact a vehicle's safety or leave structural issues

### Damage records



03/2021



**Assessment**


Sides affected

Estimated Repair Cost


€501 – €1,500

Possible Cause

Unknown



11/2021



**Assessment**

Sides affected

Rear

Estimated Repair Cost


€1,501 – €3,000

Possible Cause


Unknown

Damage Groups

Exterior body parts



02/2022



**Assessment**

Sides affected

Front

Estimated Repair Cost

€501 – €1,500

Possible Cause

Unknown

Damage Groups

Glass

**Disclaimer:** Most damage records are related to accidents, but that's not always the case. Some records come from other sources like body shops, damage claims, auctions, or vehicle inspections. These records show that the vehicle's condition was assessed, even if it wasn't due to an accident.

### Damage Glossary

**Assessment**  
Assessment is the process of evaluating the extent of damage to a vehicle. It involves inspecting the vehicle to determine what repairs are needed, estimating the costs, and deciding whether the vehicle is repairable or considered a total loss.

**Estimated Repair Cost**  
Once an incident related to a vehicle is assessed, damage data providers calculate the repair cost and present it in the currency of the country where the damage was evaluated. Therefore, this may not align with your expectations. The reasons for this may include:

- The country or state where damage to the vehicle was assessed may have higher/lower servicing costs compared to your country (spare part prices and labor prices differ between countries)
- The cost is calculated for repairs at an official service station (which is typically on the expensive end)


## Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

✓ **No issues found**  
Vehicle's location was not recorded in the area of a natural disaster

## Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

 **Note**

- Last known selling price: €23,900
- Average market price for such vehicle: €23,325
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

### BMW 318 2020 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

**Lowest price** **Average price** **Highest price**  
€21,423 €23,325 €25,267


### Market price history

### Price records
















12/2024	€24,000
01/2025	€22,800
01/2025	€23,100
04/2025	€23,900

## Specs & equipment

This specs and equipment are on record for this vehicle?

 **Note**  
Check whether the specs and equipment of this vehicle match the facts given by the seller.

### Identification and technical specifications



 <b>Make</b> <b>BMW</b>	
 <b>Model</b> <b>318</b>	
 <b>Description</b> <b>318d Touring</b>	
 <b>Variant</b> <b>Touring</b>	
 <b>Body type</b> <b>Estate</b>	
 <b>Manufacture year</b> <b>2020</b>	
 <b>Powertrain displacement</b> <b>2 L</b>	
 <b>Powertrain power</b> <b>110 kW (148 hp)</b>	
 <b>Torque</b> <b>320 Nm</b>	
 <b>Fuel type</b> <b>Diesel</b>	
 <b>Transmission type</b> <b>Automatic</b>	
 <b>Drive type</b> <b>RWD</b>	
 <b>Color</b> <b>Black</b>	
 <b>Steering wheel placement</b> <b>LHD</b>	
 <b>Number of cylinders</b> <b>4</b>	
<b>Equipment</b> As received from the manufacturer	
<b>1AG</b> LARGER-CAPACITY FUEL TANK	<b>1CB</b> CO2 CONTENT
<b>1U2</b> BMW LIGHT-ALLOY WHEEL V-SPOKE 775 RS	<b>205</b> STEPTRONIC TRANSMISSION
<b>230</b> EU-SPECIFIC ADDITIONAL CONTENTS	<b>255</b> SPORT LEATHER STEERING WHEEL
<b>2PA</b> LOCKING WHEEL BOLTS	<b>2VB</b> TYRE PRESSURE INDICATOR
<b>2VC</b> TYRE REPAIR KIT	<b>302</b> ALARM SYSTEM
<b>320</b> MODEL DESIGNATION, DELETION	<b>322</b> COMFORT ACCESS SYSTEM
<b>3AA</b> ROOF RAILS BLACK	<b>418</b> LUGGAGE-COMPARTMENT PACKAGE
<b>420</b> SUN PROTECTION GLAZING	<b>428</b> WARNING TRIANGLE
<b>430</b> INTERIOR AND EXTERIOR MIRROR PACKAGE	<b>431</b> INTERIOR REAR-VIEW MIRROR WITH AUTOMATIC ANTI-DAZZLE FUNCTION
<b>481</b> SPORT SEATS FOR DRIVER AND FRONT PASSENGER	<b>488</b> LUMBAR SUPPORT DRIVER/FRONT PASSENGER
<b>493</b> STORAGE COMPARTMENT PACKAGE	<b>494</b> SEAT HEATING FOR DRIVER AND FRONT PASSENGER
<b>4GN</b> INT.TR.FINI.WI.QUARTZ SILVER MATT,G	<b>534</b> AUTOMATIC AIR CONDITIONING
<b>544</b> DYNAMIC CRUISE CONTROL	<b>548</b> SPEEDOMETER WITH KILOMETER READING
<b>5A1</b> LED FOG LIGHTS	<b>5AL</b> ACTIVE PROTECTION
<b>5AQ</b> ACTIVE GUARD PLUS	<b>5AS</b> DRIVING ASSISTANT
<b>5DA</b> FRONT PASSENGER AIRBAG DEACTIVATION	<b>5DC</b> FOLDING REAR-SEAT HEADRESTS
<b>5DN</b> PARKING ASSISTANT PLUS	<b>6AE</b> TELESERVICES
<b>6AF</b> LEGAL EMERGENCY CALL	<b>6AK</b> CONNECTEDDRIVE SERVICES
<b>6C4</b> CONNECTEDPACKAGE PROFESSIONAL	<b>6NW</b> TELEPHONY WITH WIRELESS CHARGING
<b>6U3</b> BMW LIVE COCKPIT PROFESSIONAL	<b>6VD</b> WIFI HOTSPOT
<b>7LC</b> MODEL ADVANTAGE	<b>801</b> GERMAN VERSION
<b>851</b> LANGUAGE VERSION GERMAN	<b>879</b> GERMAN / ON-BOARD DOCUMENTATION
<b>8KB</b> OIL SERVICE INTERVAL - 24 MONTHS/25,000 KM	<b>8R9</b> REFRIGERANT
<b>8TF</b> ACTIVE PEDESTRIANS SAFETY	<b>9AA</b> OUTER SKIN PROTECTION
<b>9DB</b> BUSINESS PACKAGE PROFESSIONAL	<b>9QX</b> VORBEREITUNG FAHRERASSISTENS I



## Timeline



9 records found



The timeline of records for this vehicle



### Records



01/2020  **Country unknown**  
 **First registration**  
The record represents an administrative event. This could be related to a change of ownership, documents, etc


02/2020  **Country unknown**  
 **Was manufactured**  
The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

03/2021  **Germany**  
 **Assessment detected** ⚠  
We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

11/2021  **Germany**  
 **Assessment detected** ⚠  
We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

02/2022  **Germany**  
 **Assessment detected** ⚠  
We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

05/2023  **Germany**  
 **Was on sale**  
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

12/2024  **Poland**  
 **Was on sale**  
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

01/2025  **Poland**  
 **Was on sale**  
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

04/2025  **Poland**  
 **Was on sale**  
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

 +31 **Data sources**  
We checked 900+ data sources in 35 countries