
CARVERTICAL





Data sources We checked 900+ data sources in 35 countries


Photos

We found 43 photos of this vehicle. Scan report QR code to see all. 11/2024




Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!



Odometer

Are there signs of mileage rollbacks or discrepancies?



6 mileage records found



Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?



Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).






Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?



Emissions

How much CO2 emissions do vehicles of this model/year produce?

carVertical Insight

This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

CO₂ emissions

Emission CC	D₂ g/km
Up to 120	Your vehicle
120 - 140	emissions
140 - 155	101 g/km _{Class}
155 - 165	
165 - 190	
190 - 225	
225 +	

Specs

What specs and equipment are on record for this vehicle?

i Note

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

A	Make Peugeot
Ą	Model 5008
Ą	Body type Sedan
÷	Manufacture year 2018
77	Powertrain displacement 1.5 L

1	Powertrain power 96 kW (129 hp)	
미	Fuel type Diesel	
;;;	Transmission type Automatic	
0 <u>+</u> 0 0+0	Drive type FWD	
4	Number of seats 7	
	Category M1	
	Type Approval e2*2007/46*0534*08	
٩	Gross weight 2,210 kg	
٩	Curb weight 3,410 kg	
% }	CO2 emissions 101 g/km	
Timeline		
6 records found		
The timeline of records for this vehicle		

Records

11/2018 🔇 Country unknown

🛞 Was manufactured

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

11/2018 🚯 Country unknown

First registration

The record represents an administrative event. This could be related to a change of ownership, documents, etc



Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

01/2023 () France

$\bigvee_{O=}^{=}$ Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

10/2024 () France

🛃 Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

11/2024 🌗 France

🕵 Was on sale

This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.



Data sources

We checked 900+ data sources in 35 countries