


Renault Scénic

VIN: VF1RFA00X59915113


Diesel

2018




Generated on 05/20/2025, 05:54 PM


Scan for full report

**Purpose**


Looks good

**Odometer**


Looks good

**Legal status**

Looks good

**Damage**

Looks good

**Data sources**

We checked 900+ data sources in 35 countries


Photos

We found 51 photos of this vehicle. Scan report QR code to see all.

06/2023


Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

**No issues found**


No records of vehicle being used in irregular manner

Here's what we checked:

**Taxi**


No record found

No evidence of being used as a taxi

**Transport**


No record found

No evidence of being used as a transport vehicle

**Rental**


No record found

No evidence of being used as a rental vehicle

**Police**


No record found

No evidence of being used by police

**Demo**

No record found

No evidence of being used as a demo vehicle


**Driving school vehicle**

No record found


No evidence of being used as a driving school vehicle


Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?


**No issues found**

We didn't find any records that the vehicle was stolen.


**Note**

Police database stolen vehicle check completed in 11 countries:  +5

Here's what we checked:

**Currently wanted as stolen**


No record found


**Stolen in the past**


No record found


No past theft records found for this vehicle.


Police database stolen vehicle check completed in:


**Lithuania**


**United States**


**Slovakia**


**Sweden**


**Denmark**


**Canada**

**Hungary**

**Italy**


**Czechia**

**Slovenia**

**Romania**

Odometer

Are there signs of mileage rollbacks or discrepancies?

**Note**

- Last known mileage: 187,287 km
- Average mileage for similar models: 121,714 km
- 5 mileage records found


carVertical Insight

It seems this vehicle wasn't being used for a while. There may be a good reason, but it's still useful to learn the facts. Was it damaged? Was there an expensive issue (engine / transmission failure, etc.)? Was there a mileage rollback?

Odometer records	
01/2018	11 km
10/2019	54,010 km
04/2022	148,132 km
06/2023	187,284 km
01/2025	187,287 km


Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

**No issues found**


No records about the legal status of this vehicle were found

Legal

**Technical inspection (MOT)**


Passed

04/2022



Has successfully passed technical inspection

Valid until 04/2024


**Scrap**

No record found

No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).


**No issues found**

Damage records

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters


Has the vehicle's location been recorded in the area of a natural disaster?

**No issues found**

Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

**Note**

- Last known selling price: €13,400
- Average market price for such vehicle: €13,932
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Renault Scénic 2018 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price

Average price

Highest price

€12,495

€13,932


€14,998

Market price history

Price records	
01/2025	€14,600
01/2025	€14,300
04/2025	€13,400

Emissions

How much CO2 emissions do vehicles of this model/year produce?

**carVertical Insight**


This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

CO2 emissions

Emission CO2 g/km


Specs & equipment

What specs and equipment are on record for this vehicle?


**Note**

Check whether the specs and equipment of this vehicle match the facts given by the seller.


Identification and technical specifications

**Make**


Renault

**Model**


Scénic

**Description**


Scenic 4 (Xfa)

**Variant**


Xmod

**Body type**


Sedan

**Manufacture year**


2018

**Powertrain displacement**


1.5 L

**Powertrain power**


81 kW (109 hp)

**Fuel type**


Diesel

**Transmission type**


Automatic

**Drive type**


FWD

**Color**


Silver

**Number of gears**


7

**Number of seats**


7

**CO2 emissions**


104 g/km

**ACCESSORY SOCKET**


WITH ACCESSORY SOCKET 2 (PRIAC2)

**ADJUSTMENT OF FRONT SEAT BELTS**


HEIGHT ADJUSTABLE SEATBELTS (CEAVRH)

**AIRBAG CANCEL**


DECONNEX AIRBAG PASS (AIRBDE)

**ANTI-THEFT DEVICES**


IMMOBILISER DEVICE (ANTID)

**BATTERY POWER TRACTION**


WITHOUT BATTERY ENERGY (SSCABA)

**BRAKING ASSISTANCE**


BOOSTER EMERGENCY BRAKING (AFURGE)

**CLIMATIC CONSTRAINT HOT COUNTRY**


WO CLIMAT CONST WARM COUN (SSCCPC)

**COMMERCIAL EVENT**


COMPLEMENTARY OBJECT (SAN822)

**COMMERCIAL EVENT MANAGEMENT 3**


COMPLEMENTARY OBJECT (SANF78)

**COMMERCIAL VERSION SUPPLEMENT 5**


WO COMMERCIAL VERSION (VSNOR)

**CONDITIONING**


STANDARD PROTECTION (COND0)

**COUNTRY OF APPLICATION OF TECHNICAL LEGISLATION**


TECHNICAL REG : RP00 (TLRP00)

**DAYTIME RUNNING LIGHTS**


DAYTIME RUNNING LIGHTS 2 (FDIU2)

**DOOR OPENING REMOTE CONTROL TYPE**


433 MHZ HANDMA DOOR OPENI (SOP03C)

**DRIVER'S HANDBOOK**


ITALIAN GLOVE BOX LITERAT (NOTITA)

**DUST PROTECTION**


WITH DUST KIT (KITPOU)

**ELECTROMOTOR DOOR LOCKING**


ELECTRIC DOOR LOCKING (CPE)

**EMERGENCY CALL AND BREAKDOWN**


WITHOUT CALL FONCTION (SSCALL)

**EXTERIOR REAR VIEW MIRRORS**


DOOR MIRRORS 04 (RET04)

**FORWARD EMERGENCY BRAKING**


ADV EM BRAKING URBAN 5 (AEB505)

**FRONT AND REAR PROXIMITY RADAR**


COMPLEMENTARY OBJECT (SAN263)

**FRONT SEAT SUITABLE FOR CHILDREN**


ISOFIX SEAT (ISOFIX)

**FRONT SIDE AIRBAG**


FRONT SIDE AIRBAG + HEADA (ABLAVI)

**GEAR SHIFT INDICATOR**


WITH GEAR SHIFT INDICATOR (AVGSI)

**GEOGRAPHIC COUNTRY**


GEO COUNTRY ITALY (ITA01)

**HEAD UP DISPLAY (HUD)**


WITHOUT PRESTATION (SPRPHMD)

**HEATED WINDSHIELD**


NON-HEATED WINDSCREEN (PBNCH)

**INTERIOR COLOUR STYLING**


INTERIOR HARMONY 01 (HARM01)

**INTERNAL NAME**


NO NAME (SSAPEL)

**LANE KEEP**


WITH LDW SYSTEM TYPE 1 (DLIGM1)

**MAKE OF TYRES**


TYRE BRAND: UNMARKED FITT (BANAL)

**DETECTOR SAFETY**


COMPLEMENTARY OBJECT (SAND96)

**DRIVER ATTENTION ALERT**


CUST EXPECT-DETECTION SLE (PRDEND)

**DRIVING MODE CONTROL**


WITHOUT MULT EXP (SSMLEX)

**ELECTRONIC TOLL COLLECTION**


WO ELECTRONIC TOLL SYS SP (SSPTLP)

**ELECTRONIC STABILITY PROGRAM**


ENGINE PRODUCTION PLANT

**ENGINE PRODUCTION PLANT**


(D) VALLADOLID MOTORES (SPAIN) (APV002_D)

**FIRE EXTINGUISHER**


WITHOUT FIRE EXTINGUISHER (SEXTIN)

**FRONT AND REAR BODY CROSSMEMBER**


WITHOUT HEADLIGHT-WASHER (SLAVPH)

**FRONT HEADREST TYPE**


FRONT HEADREST 01 (ATAV01)

**FRONT SEAT TYPE**


FRONT SEAT TYPE N 07 (SGAV07)

**FRONT TYRES**


195/55 R20 (95)H, 6.50 J 20 - 33

**GEARBOX PRODUCTION PLANT**


(A) NEUENSTEIN / GETRAG (GERMANY) (APV003_A)

**GLASSES STORAGE**


WITHOUT GLASSES STORAGE (SRGTLU)

**HEADLIGHT WASHER**


HIGH MOUNTED STOP LAMP

**HIGH MOUNTED STOP LAMP**


WITH RAISED BRAKE LIGHT (FSTPO)

**INTERIOR REAR VIEW MIRROR**


RRVIEW MIR DAYLIGHT/NIGHT (RETRJN)

**INVARIANT PROCESS SHEET MODEL**


MODEL ROUTING SHEET (XFA1ML)

**LUGGAGE RETAINING DEVICE**


WITHOUT A NET FOR HOLDING LUGGAGE (SFIRBA)

**MARKETING VERSION**


COMMERCIAL VERSION (VEC021)

**MISCELLANEOUS BENEFITS TER**


COMPLEMENTARY OBJECT (SAN503)

**NAVIGATION/SMARTPHONE IMITATION**


SMARTPHONE IMITATION (SPMIR)

**ON-BOARD WARRANTY/SERVICES**


SERVICES BOOKLET (RSANA1)

**PARKING ASSIST SYSTEM**


FR+RR SENSORS (ITPK4)

**PASSENGER COMPARTMENT HEATING TYPE**


AIR-CONDITIONING TYPE N3 (CA03)

**PEDAL MATERIAL**


COMPLEMENTARY OBJECT (SANA38)

**PLANT ASSEMBLY LINE**


ASSEMBLY LINE 1 (CHMON1)

**PRICING**


COMPLEMENTARY OBJECT (NOH02)

**REAR CENTRE SEATBELT**


3-POINT CENTRE SEATBELT (CMAR3P)

**REAR BLIND BLIND**


REAR BLIND 01 (RIDO01)

**REAR TYRES**


195/55 R20 (95)H, 6.50 J 20 - 33

**REAR WINDOWDOWN**


ELECTRIC ANTI-PINCH (LVARAP)

**ROAD SEVERITY**


TYPE OF ROAD SEVERITY 1 (TRSEV1)

**ROUTING SHEETS COUNTRY**


ITALY (ITAL)

**SEAT COVERS**


FABRIC SEAT-LINING N 02 (DRAP02)

**SEAT TRIMS**


VELVET CLOTH (DRA)


**SECURITY DISTANCE GESTION**

WO SECUR DIST GEST (SSDWGE)


**SIDE APPROACH WARNING SYS**

WITHOUT SIDE APPROACH WAR (SRDLAT)


**SPARE WHEEL**

**NAVIGATION MAP**


STANDARD MAPPING (MAPSTD)

**NUMBER OF BODY COLORS**


ONE COLOR (ITON)

**OVERSPEED AUDIBLE WARNING DEVICE**


WITHOUT EXCESS SPEED HORN (SASURV)

**PARKING BRAKE TYPE**


ELECTRICAL PARKING BRAKE (FPASS)

**PASSENGER COMPARTMENT THERMAL REQUIREMENT**


REQUIREMENT 1 (THABT1)

**PEDESTRIAN COLLISION WARNING**


FRONT COLL DETECTOR 1 (DCOLS1)

**PLANT MARKING FOR COMPLEX START**


COMPLEMENTARY OBJECT (SAN593)

**PROTECTION ELEMENTS**


DR*AS AIRBAG (AIRBA2)

**REAR HEADREST TYPE**


REAR HEADREST TYPE 1 (ATAR01)

**REAR SEAT TYPE**


REAR SEAT N 02 (SGAR02)

**REAR WINDOW**


HEATED REAR SCREEN (LAC)

**REFRIGERATOR**


WITHOUT COOL DRAWER (STIREF)

**ROOF RACK/BARS**


LONGITUDINAL BARS (BARLON)

**SEAT BELT REMINDER**


SEAT BELT WARN TYPE 5 (ALOU05)

**SEAT HEATER AND COOLER**


NON-HEATED SEAT (SGSCH4)

**SEATS: 3RD ROW**


2 SEATS - THIRD ROW SEATS (2P3RAN)


**SERVICE DONGLE**

COMPLEMENTARY OBJECT (NOH14)


**SMOKER'S ACCESSORIES**

WITHOUT SMOKER ACCESSORIE (SANACF)


**SPECIAL BUILD (FACTORY)**

**MISCELLANEOUS BENEFITS TER**


COMPLEMENTARY OBJECT (SAN503)

**NAVIGATION/SMARTPHONE IMITATION**


SMARTPHONE IMITATION (SPMIR)

**ON-BOARD WARRANTY/SERVICES**


SERVICES BOOKLET (RSANA1)

**PARKING ASSIST SYSTEM**


FR+RR SENSORS (ITPK4)

**PASSENGER COMPARTMENT HEATING TYPE**


AIR-CONDITIONING TYPE N3 (CA03)

**PEDAL MATERIAL**


COMPLEMENTARY OBJECT (SANA38)

**PLANT ASSEMBLY LINE**


ASSEMBLY LINE 1 (CHMON1)

**PRICING**


COMPLEMENTARY OBJECT (NOH02)

**REAR CENTRE SEATBELT**


3-POINT CENTRE SEATBELT (CMAR3P)

**REAR BLIND BLIND**


REAR BLIND 01 (RIDO01)

**REAR TYRES**


195/55 R20 (95)H, 6.50 J 20 - 33

**REAR WINDOWDOWN**


ELECTRIC ANTI-PINCH (LVARAP)

**ROAD SEVERITY**


TYPE OF ROAD SEVERITY 1 (TRSEV1)

**ROUTING SHEETS COUNTRY**


ITALY (ITAL)

**SEAT COVERS**

FABRIC SEAT-LINING N 02 (DRAP02)

**SEAT TRIMS**

VELVET CLOTH (DRA)

**SECURITY DISTANCE GESTION**

WO SECUR DIST GEST (SSDWGE)