

CARVERTICAL

Purpose

✓ Looks good

Peugeot 3008

VIN: VF3MCYHZUMS176236 Diesel 2021

Odometer

✓ Looks good

Legal status

✓ Looks good

9]6

Generated on 05/20/2025, 05:53 PM

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months. Lowest price

Emissions

Up to 120

120 - 140

140 - 155

Specs

Note

Body type Van

2021

1.5 L

Fuel type

Manufacture year

Powertrain power 96 kW (129 hp)

Number of seats

CO2 emissions

The timeline of records for this vehicle

manufacturer. The date may be approximate.

state) overwrites the vehicle's actual location.

Records

Powertrain displacement

carVertical Insight

Your vehicle

emissions 6 g/km

Class A

What specs and equipment are on record for this vehicle?

€20,487

provide a 100% guarantee.

Natural disasters

No issues found

Market value

Note

Has the vehicle's location been recorded in the area of a natural disaster?

Average market price for such vehicle: €22,170

Peugeot 3008 2021 market value today

Vehicle's location was not recorded in the area of a natural disaster

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

• Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Average price

€22,170

This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

Highest price

€24,138

CO₂ emissions Emission CO₂ g/km

How much CO2 emissions do vehicles of this model/year produce?

Identification and technical specifications Make Peugeot 3008

Check whether the specs and equipment of this vehicle match the facts given by the seller.

No damage found

Right side

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to

Diesel Transmission type **Automatic**

6 g/km Timeline 4 records found

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the

The record represents an administrative event. This could be related to a change of ownership, documents, etc

07/2021 🚱 Country unknown

11/2024 () Italy Was on sale This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or

Was deregistered

12/2024 () Italy

or similar.

First registration

07/2021 () Italy

Data sources

We checked 900+ data sources in 35 countries

The indicated record represents an administrative event. This could be related to a change of ownership, change of documents,