


Ford Edge

VIN: 2FMTK4A39JBB46657 2018

Generated on 05/20/2025, 12:07 PM



Scan for full report



Purpose

Looks good



Odometer

Looks good



Legal status

Looks good



Damage

Looks good




Data sources

We checked 900+ data sources in 35 countries

Photos

We found 38 photos of this vehicle. Scan report QR code to see all.

10/2024



Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!



No issues found

No records of vehicle being used in irregular manner

Here's what we checked:



Taxi

No record found

No evidence of being used as a taxi



Transport

No record found

No evidence of being used as a transport vehicle



Rental

No record found

No evidence of being used as a rental vehicle



Police

No record found

No evidence of being used by police



Demo

No record found

No evidence of being used as a demo vehicle



Driving school vehicle

No record found

No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?



No issues found

We didn't find any records that the vehicle was stolen.



Note

Police database stolen vehicle check completed in 11 countries: +5

Here's what we checked:



Currently wanted as stolen

No record found



Stolen in the past

No record found

No past theft records found for this vehicle.

Police database stolen vehicle check completed in:

Slovakia United States Lithuania

Czechia Romania Slovenia

Hungary Italy Sweden

Denmark Canada


Odometer

Are there signs of mileage rollbacks or discrepancies?



Note

- Last known mileage: 147,689 km
- Average mileage for similar models: 115,944 km
- 4 mileage records found



Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?



No issues found

No records about the legal status of this vehicle were found

Legal



Technical inspection (MOT)

Passed

10/2024 Has successfully passed technical inspection



Scrap

No record found

No record that vehicle was marked as scrapped


Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).



No issues found

Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?



No issues found

Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?




Note

- Last known selling price: €21,500
- Average market price for such vehicle: €16,841
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Ford Edge 2018 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.




Emissions

How much CO2 emissions do vehicles of this model/year produce?

carVertical Insight  
This vehicle has average emissions. It will likely incur standard emission taxes.

CO2 emissions

Emission CO2 g/km



Specs

What specs and equipment are on record for this vehicle?



Note

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

Make Ford

Model Edge

Body type Sedan

Manufacture year 2018

Model year 2018

Powertrain displacement 2 L

Powertrain power 154 kW (207 hp)

Transmission type Automatic

Drive type AWD

Color White

Number of seats 5

CO2 emissions 152 g/km

Timeline

7 records found

The timeline of records for this vehicle

Records

06/2018 Country unknown

Was manufactured

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

06/2018 Italy

First registration

The record represents an administrative event. This could be related to a change of ownership, documents, etc

07/2024 Italy

Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

10/2024 Country unknown

Was inspected

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

10/2024 Italy

Was on sale

This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

10/2024 Italy

Was deregistered

The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.

04/2025 Poland

Was on sale

This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.



Data sources

We checked 900+ data sources in 35 countries