





Opel Grandland X
VIN: WV0ZRHNS6L6026809 Generate


Generated on 06/09/2025



Scan for full report


 Purpose


 Looks good


 Mileage

 Looks good

 Legal status

 Looks good

 Damage















 Looks good

 **Data sources**
We checked 900+ data sources in **40 countries**

Photos

We found **25 photos** of this vehicle. Scan report QR code to see all.


04/2024




+15 photos


Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!


 **No issues found**
No records of vehicle being used in irregular manner


Here's what we checked:

 Taxi


 No record found


No evidence of being used as a taxi

 Transport


 No record found


No evidence of being used as a transport vehicle

 Rental


 No record found


No evidence of being used as a rental vehicle

 Police

 No record found

No evidence of being used by a police


 Demo


 No record found

No evidence of being used as a demo vehicle

carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025


 **Driving school vehicle**

 No record found


No evidence of being used as a driving school vehicle

Theft


Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?


 **No issues found**
We didn't find any records that the vehicle was stolen.


Note


Police database stolen vehicle check completed in **11 countries**:  +5

Here's what we checked:

 Currently wanted as stolen

 No record found

 Stolen in the past

 No record found

No past theft records found for this vehicle.

Police database stolen vehicle **check completed in:**

 Czechia  Romania  Slovenia  Slovakia  Italy  Hungary  Canada  Denmark  Lithuania  United States

Sweden

Mileage


Are there signs of mileage rollbacks or discrepancies?

 **Note**

- Last known mileage: 200,693 km
- 15 mileage records found


carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025





Legal status


Has the vehicle passed technical inspection? Was it marked as scrapped?


 **No issues found**
No records about the legal status of this vehicle were found


Legal

 Technical inspection (MOT)

 Passed

07/2024  Poland Has successfully passed technical inspection


 Scrap

 No record found


No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

 **No issues found**

Damage records



Left side

Right side

Rear


Front

No damage found

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.


Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

 **No issues found**
Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

 **Note**

- Last known selling price: €11,100
- Average market price for such vehicle: €16,767
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Opel Grandland X market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price


Average price

Highest price

€15,846

€16,767

€18,025




Specs & equipment


What specs and equipment are on record for this vehicle?

 **Note**
Check whether the specs and equipment of this vehicle match the facts given by the seller.


Identification and technical specifications

 Make


Opel

 Model


Grandland X

 Description


Grandland X

 Body type


SUV

 Model year


2020

 Powertrain displacement


1.2 L

 Powertrain power


96 kW (129 hp)

 Fuel type


Gasoline

 Transmission type


Manual

 Color


Grey

 Steering wheel placement


LHD

 Engine description


ENG 1.2 EB2ADTS (O3S)

 Number of seats

5

 Engine code

10TMA40043714

 Gross weight


1,900 kg


carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.


VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025


Equipment


As received from the manufacturer


 230V POWER OUTLET


 SEAT COMFORT PACK ONE


 LAMP REAR TAIL LED


 INDICATOR ST BELT WARNING DRIVER


 SENSOR IND. LANE KEEP ASSIST


 ANTENNA - DIVERSITY


 6 LOUDSPEAKERS CUSTOM


 VEHICLE STATEMENT ECE ORG


 GEARING CODE


 VIN MODEL YEAR 2020


 TYR SPARE 135/80R18 SL104V BW1


 PILOT TRIAL RUN #1


 CONTROL SEAT MAN CUS EXTN PASS


 VM RETAIL USE ONLY


 WINTER PACK


 VM ADMIN USE ONLY


 14


 PARK & GO PACK 1


 ACTIVE EMERGENCY BRAKINGSYSTEM


 INDIC. SEAT BELT WARNING RR


 INDICATOR ST BELT WARNING PASS


 TPMs - TYRE PRESSURE MONITOR


 SENSOR TRAFFIC SIGN RECOGNITIO


 CONTROL SEAT MAN CUS EXTN DR


 SKID PLATE FRONT 1 WITH GRAIN


 SEAT RR SPLIT FOLD CTR ARMREST


 EVAPORATIVE SYS.EURO6 EMISSION


 IDENTIFICATION MODEL #1


 BREAKING POINT 2020 1/2 M.Y

 WITHOUT WAX PROTECTION

 VM ADMIN USE ONLY


 INVENTORY USE ONLY


 RESTRAINT HEAD POWER DRIVER


 15


carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.


VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025


 WINDSHIELD ACOUSTIC PVB


 PROVISIONS FOR RESTRAINING NET


 REAR CENTER HEAD RESTRAINT


 SALES PACKAGE 5 - STAR EUNCAP


 LUMBAR DRIVER SEAT POWER 4WAY


 VEHICLE TYPE PASSENGER CAR


 WASHER + WIPER BACK WINDOW


 LAMP INTR AMBIENT UPLEVEL


 PASSENGER AIRBAG MANUAL CUTOFF


 WIPER SYS MOISTURE SENSITIVE


 PSA SALES REGION PKG - GRP 01


 NETHERLANDS-MANDATORY


 MIRROR I/S FRT VAN SUNSHADE DS


 TRAY LOAD FLOOR STORAGE

 EQUIP. PACKAGE CO2-REDUCTION

 TRAY FRT FLR CONS CUP HOLDER

 POCKET FRONT SEAT BACK LH

 VEHICLE FUEL GASOLINE E10

 47

 RESTRAINT HEAD FRT SEAT UP/D

 DARK TINTED REAR WINDOWS

 CHILD RR SEAT REINFORCED

 LOCK CTR PASSIV ENTR FRNT DOOR

 LUMBAR PASS SEAT POWER 4WAY

 AIR,FRT DR&CO SIDE&ROOF FRT&RR

 GLAZED REAR DOOR W/WASHER+HEAT

 LAMP INTR AMBIENT

 INTERIOR TRIM JET BLACK

 COVER CARGO FABRIC


 DUAL ZONE ELEC CLIMATE CONTROL

 SIGHT & LIGHT PACK 1 PACKAGE

 HANDLE O/S DR COLORED

 ADJUSTABLE DRIVER'S ARMREST

 MIRROR IS/RT LV SENSITIVE

 MIR O/S RC EL HT CNVX PWR/F PUD


 POCKET FRONT SEAT BACK RH


 ELECTRONIC STABILITY PROGRAMME


 48


carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.


VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025


 PACKAGE TRIM LEVEL 3


 ITC CLOTH/VINYLV LV 3.2 JET BLK


 ENGINEERING YEAR 2020


 ABS 16" FRT & RR DISC POWER


 CRUISE CNTRL AUTO ELEC. SPEED


 POWER OUTLET TRUNK


 RECEPTACLE ELECTR FRT CONSOLE


 SEAT COMFORT PACK TWO


 LEFT HAND DRIVE


 TRANS-MAN 6 SPD 189MM MB6 PSA


 MOLD B/S UP/R SI ROOF LI CHROME


 STEERING WHEEL LEATH. 3 SPOKES


 MANUAL CHILD LOCK SYSTEM


 EMISSION SYSTEM EURO 6D


 ENG 1.2 EB2ADTS


 TRIM LEVEL STEERING


 TYR ALL215/65R17 XL103V BW HW1


 WHL SPARE 18X4.0 B STEEL DES1


 8


 MOONSTONE GREY


 FASCIA INSERT RR LOW SKIDPLATE


 RADIO INTELLILINK RF900 TOUCH


 BRAKE PARKING POWER OPERATED


 HILL START ASSIST


 HEATER DUCT RR (2ND POSN)


 START/STOP ENGINE CONTROL


 REFRIGERANT LOW GWP


 LOCAL PACKAGE


 MARKETING AREA - EUROPE


 TRANS-MAN MERCHANDISED EQUIP.


 MAN.TILT TELESCOPING STEERING


 RESTRAINT SEAT BELT TENSIONER


 POWER STEER NON VAR ELECTRIC

 MODEL UPGRADE 03

 SALES PACKAGE COMFORT PSA ONLY


 WHEEL 17X7 J ALU DESIGN 1


 RESTR SEAT BELT PRETENS RR

 80


carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.


VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025


 ISOFIX - FRONT PASSENGER SEAT


 HEADLAMPS LED


 ADAPTIVE FORWARD LIGHTING


 LIFT GATE POWER HANDS FREE


 CONTROL INTELLIGENT HIGH BEAM


 LAMP INTR ROOF RR WITH SWITCH


 HORN SINGLE NOTE


 SPEEDOM. KM


 DIG. AUDIO SYS INT. DAB/DAB+

 CONTROL STEERING WHEEL RADIO


 INFO DISPLAY MULTI COLOR GRAPH


 81

 LAMP FRT FOG ECE


 HEADL. CNTRL AUTOM ON-OFF


 TRIM CLOTH/VINYLV LV3.2 JET BLK

 LETTERING "ECOTEC" REAR

 STOPLAMP CENTER HIGH MOUNTED


 ERGONOMIC SPORTS FRONT SEATS


 COMM SYSTEM UNIT 3S BASIC

 LAMP IN LUGGAGE COMPARTMENT

 INFORMATION-COMPUTER


 FRONT AND REAR PARKING SENSORS


 SENSOR ULTRASONIC BLINDSPOT DT

 82

carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.


VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/09/2025


 TIMELINE

 7 records found


The timeline of records for this vehicle


Records

06/2020 

 First registration

The record represents an administrative event. This could be related to a change of ownership, documents, etc.

04/2024 

 Was on sale

This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

carVertical
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

VIN: WV0ZRHNS6L6026809 | Generated on 06/09/2025 | Expires on 07/