Opel Movano VIN: W0VMR8601LB207105 Diesel				
Generated on 06/09/2025 Scan for full report				
Purpose 🗸 Looks good 🙆 Mileage 🗸 Looks good 🚳 Legal status 🗸 Looks good				
Damage 🕜 Needs attention				
+36 Data sources We checked 900+ data sources in 40 countries				
Photos				
We found 60 photos of this vehicle. Scan report QR code to see all. 09/2024				
+50 photos				
Purpose Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!				
No issues found No records of vehicle being used in irregular manner				
Here's what we checked:				
Taxi V No record found No evidence of being used as a taxi				
Transport V No record found No evidence of being used as a transport vehicle				
Characterization No evidence of being used as a rental vehicle Characterization No record found No evidence of being used by police				
Demo V No record found No evidence of being used as a demo vehicle				
CARVERTICAL VIN: WOVMR8601LB207105 Generated on 06/09/2025 Expires on 07/09/2025 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.				
Driving school vehicle Vorecord found No evidence of being used as a driving school vehicle				
Theft Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?				
No issues found We didn't find any records that the vehicle was stolen.				
Note Police database stolen vehicle check completed in 11 countries: +5				
Here's what we checked:				
Currently wanted as stolen Vorecord found Stolen in the past Vorecord found No past theft records found for this vehicle.				
Police database stolen vehicle check completed in: Czechia 🖢 Slovenia 🌔 Romania 🍅 Slovakia 🌓 Italy 🍧 Hungary 🐠 United States 🍚 Lithuania 🛟 Denmark (*) Canada Sweden				
Mileage Are there signs of mileage rollbacks or discrepancies?				
 Note Last known mileage: 204,671 km 14 mileage records found 				



CARVERTICAL Generated on 06/09/2025 Expires on 07/09/2025 VIN: W0VMR8601LB207105 VIN: WUVMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/20 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?



CARVERTICAL

VIN: W0VMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/20. This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Unknown

Generated on 06/09/2025 Expires on 07/09/2025

VIN: W0VMR8601LB207105

Right side

We grouped these damage records together in this PDF report - they appear to describe the same event, as they share consistently similar dates, locations, and details. To view all available details and ensure you're seeing the most detailed and up-to-date information, please refer to the digital report on our website.

Disclaimer: Most damage entries are related to traffic accidents, but not exclusively. Some entries may end up on the report for different reasons, such as damage assessments, auctions, vehicle inspections, repairs and other similar events, actions or circumstances. Entries like these may indicate, for example, that the vehicle was inspected and assessed at an authorised service centre, or that repairs, warranty service, diagnostics, vehicle inspection or other similar services were performed. These vehicle inspections or assessments may be done due to damage caused during a traffic accident, but also for other reasons, such as legal requirements and/or processes, information published by the manufacturer, warranty or nonwarranty repairs, correction of poorly performed repairs, or damage not related to traffic accidents (e.g. theft, mechanical damage, etc.). It is important to note that such entries do not necessarily indicate the consequences of a traffic accident - they may also be related to the use, maintenance or operation of the vehicle in accordance with the requirements and circumstances set by the manufacturer or third parties.

Damage Glossary

Damage Damage refers to any physical harm or loss sustained by a vehicle, such as scratches, dents, or broken parts. It can result from accidents, weather, theft, or other incidents and may affect the car's appearance or performance. Estimated Repair Cost

Once an incident related to a vehicle is assessed, damage data providers calculate the repair cost and present it in the currency of the country where the damage was evaluated. Therefore, this may not align with your expectations. The reasons for this may include: The country or state where damage to the vehicle was assessed may have higher/lower servicing costs compared to your country (spare part prices and labor prices differ between countries) The cost is calculated for repairs at an official service station (which is typically on the expensive end)

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

No issues found

Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?



• Average market price for such vehicle: €16,971 Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

Opel Movano market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

CARVERTICAL

VIN: W0VMR8601LB207105 Generated on 06/09/2025 Expires on 07/09/2025 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Lowest price	Average price	Highest price
€16,440	€16,971	€17,668

Specs & equipment

What specs and equipment are on record for this vehicle?

Note 8

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

A	Make Opel
Ą	Model Movano
	Description Movano
2	Body type

Van

9

÷	Model year 2020
77	Powertrain displacement 2.3 L
A	Powertrain power 100 kW (134 hp)
마	Fuel type Diesel

	Diesel
ല്പ	Transmission type

- 99 Manual Drive type 010 010
- FWD
- Color
- 2 White

VIN: W0VMR8601LB207105 Generated on 06/09/2025 Expires on 07/09/2025 VIN: W0VMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/20. This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created. CARVERTICAL

Number of doors -- 5

7 7	Number of cylinders
የደ	4

Engine description **4** ENG-4 CYL 2.3L FAM D2 E06T2 (O4R)

Equipment

As received from the manufacturer

0	1
RADIO AM/FM/DAB/USB/BT/NAV	TRIM COLOUR - COLOUR CHARCOAL
10	11
SEAT BENCH ROW 3 DELETE	SEAT REAR - DELETE (2ND POSN)
12	13
SEAT FRONT BENCH WITH H/REST	WINDOW RR QTR DELETE
14	15
SEAT PASSENGER FRONT BENCH	
16 WINDOW ALL TINTED	17 BULKHEAD WITHOUT WINDOW
18	19
ELECTRIC WINDOW - ONE TOUCH	VEHICLE TYPE COMMERCIAL VEHICL
2	20
TRIM CLOTH PULSE	DOOR RH WITHOUT WINDOW
21	22
PANEL BODY SIDE LH W/O WINDOW	REINFORCED HEATING ELECTRIC
23	24
GVW RATING 7 700 LBS	REAR WINDOW DELETE
25	26
AIR CONDITION FRT AUTO CONTROL	WIPER SYS MOISTURE SENSITIVE
27	28
LOCK REMOTE SIDE&RR 3 FUNCT	NETHERLANDS-MANDATORY
29	3

RESTRAINT CARGO-TIE DOWN FLOOR

CARVERTICAL VIN: W0VMR8601LB207105 Generated on 06/09/2025 Expires on 07/09/2025 VIN: WOVMR8601L8207105 | Generated on 06/09/2025 | Expires on 07/09/20 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

MAP CODES WESTERN EUROPE

30	31
DRIVER I.DISP.LANG. DUTCH	ARMREST FRONT SEAT
32 MIRRORS ELEC OP/HT CONVEX	33 WHEELBASE 170 INCH
34	35
SUSP SYSTEM FRT & RR ACTIVE	CHASSIS FRONT WHEEL DRIVE-FWD
36 POLAR WHITE	37 ENGINEERING YEAR 2020
38	39
FILTER EXHAUST SYSTEM PARTICLE	CRUISE CONTROL
4 NAVIGATION SYSTEM TOUCH SCREEN	40 RECEPTACLE ELECTR. ACCESSORY
41	42
REFRIGERANT AIR CONDITIONING	GENERATOR 185 AMP
43 LEFT HAND DRIVE	44 LOCAL PACKAGE
45	46
TRANS-MAN 6 SPO/DR	EU-EQUIPMENT
EMISSION SYSTEM EURO 6D-TEMP	EXHAUST SELECT CATALYTIC REDUC
FUEL TANK 80L 21 GAL	EQUIPMENT CO2-REDUCTION STEP 2
50	51
TYRE TREAD ALL HIGHWAY	ENG-4 CYL 2.3L FAM D2 E06T2 53
GTE TRANSLATION	BODY LENGTH STD. REAR OVERHANG
54	55
FULL SIZE SPARE WHEEL	COVER WHEEL CENTER
PERFORMANCE DECREASE LEVEL 1	MUD FLAPS FRONT
58	59
WHEEL CONFIGURATION RR SINGLE	APPEARANCEPACK.CHROME INTERIOR
6 PANEL TRIM-NONE LEVEL2 PART.	60 ROOF HEIGHT HIGH
61	62
SALES REGION EUROPE	LAMP FRT FOG ECE

CARVERTICAL VIN: W0VMR8601LB207105 Generated on 06/09/2025 Expires on 07/09/2025 VIN: W0VMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/20. This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

4

6	3	

LAMP	SYS	DAY	RUNNING	LIGH	LED
C.F.					

63	64
LAMP SYS DAY RUNNING LIGH LED	TRIM CLOTH PULSE
65	66
TACHOGRAPH NONE	GOVERNOR SPEED CONTROL NONE
67	68
EFFECTIVE POINT CONTROL-PHASE2	PARTS PKG/ROAD COND. LEVEL 1
69	7
HEADLAMP LEVELLING DEVICE	ACCESSORY SIDE OBSTACLE DETECT
70	71
SPEEDOM. KM	PARK ASSIST REAR CAMERA/RADAR
72	73
RECEIVER NAVI AND TRAFFIC INFO	THEFT DETER. EL UNAUTH. ENTRY
74	75
BUMPER RR STEP - NONE	GEARING CODE
76	77
VIN MODEL YEAR 2020	FUEL ECONOMY EXTRA
78	79
POLLEN FILTER	LCV INDEX 27
8	80
DOOR RR 250/270 ANGLE N/GLAZED	IDENT. EFFECTIVE POINT CONTROL
81	82
GERMANY EQUIPMENT ADDITIONAL	MARKET BRAND OPEL
83	84
VM RETAIL USE ONLY	VM ADMIN USE ONLY
85	86
WINTER PACK	INVENTORY USE ONLY
87	9
VM ADMIN USE ONLY	GREY-INTERIOR TRIM

Timeline

9 records found

The timeline of records for this vehicle

Records

CRRVERTICAL VIN: WOVMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/2025 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

VIN: W0VMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/2025 **CARVERTICAL** VIN: WUVMR8601LB207105 | Generated on 06/09/2025 | Expires on 07/09/20 This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital car/vertical report available on our website. While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

10/2024 🕳 Poland

Was insured

The vehicle was insured in this country (or state). The record may refer to all kinds of insurance (third-party liability, KASKO, etc.) and reinsurance events. From: 10/10/2024 To: 11/08/2024

10/2024 🕳 Poland

Was registered

The record represents an administrative event. This could be related to a change of ownership, documents, etc

+36 Data sources

We checked 900+ data sources in 40 countries