





Opel Grandland X
VIN: W0V2CYHZ9K5037545 2019
Generated on 05/20/2025, 03:42 PM




Scan for full report

**Purpose**
✓ Looks good

**Odometer**
✓ Looks good

**Legal status**
✓ Looks good


**Damage**
✓ Looks good

 +31 **Data sources**
We checked 900+ data sources in 35 countries

Photos


We found **94 photos** of this vehicle. Scan report QR code to see all.

10/2024





Purpose


Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!


**No issues found**
No records of vehicle being used in irregular manner


Here's what we checked:


**Taxi** ✓ No record found No evidence of being used as a taxi

**Transport** ✓ No record found No evidence of being used as a transport vehicle

**Rental** ✓ No record found No evidence of being used as a rental vehicle


**Police** ✓ No record found No evidence of being used by police



**Demo** ✓ No record found No evidence of being used as a demo vehicle

**Driving school vehicle** ✓ No record found No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

**No issues found**
We didn't find any records that the vehicle was stolen.

**Note**
Police database stolen vehicle check completed in **11 countries**:  +5

Here's what we checked:

**Currently wanted as stolen** ✓ No record found

**Stolen in the past** ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle **check completed in:**

 Sweden

 Hungary

 Italy


 United States


 Lithuania

 Czechia

 Slovenia

 Romania


 Slovakia

 Canada


 Denmark

Odometer

Are there signs of mileage rollbacks or discrepancies?

**Note**

- Last known mileage: 200,990 km
- 10 mileage records found




Odometer records	
01/2019	10 km
10/2019	29,055 km
07/2020	59,296 km
05/2021	89,992 km
12/2021	112,451 km



Odometer records	
08/2022	134,232 km
12/2022	149,827 km
01/2023	152,601 km
10/2024	200,989 km
04/2025	200,990 km

Legal status


Has the vehicle passed technical inspection? Was it marked as scrapped?

**No issues found**
No records about the legal status of this vehicle were found

Legal


**Technical inspection (MOT)** **Passed** 01/2023  Italy Has successfully passed technical inspection

Valid until 01/2025


**Scrap** ✓ No record found No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

**No issues found**


Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

**No issues found**
Vehicle's location was not recorded in the area of a natural disaster

Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

**Note**

- Last known selling price: €13,200
- Average market price for such vehicle: €17,294
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!


Opel Grandland X 2019 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.

Lowest price

Average price


Highest price



Price records	
04/2025	€13,200


Emissions

How much CO2 emissions do vehicles of this model/year produce?

**carVertical Insight**
This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.


CO2 emissions

Emission CO₂ g/km



Specs & equipment

What specs and equipment are on record for this vehicle?

**Note**
Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

**Make**
Opel


**Model**
Grandland X

**Description**
Grandland X


**Body type**
SUV


**Manufacture year**
2019


**Model year**
2019

**Powertrain displacement**
1.5 L

**Powertrain power**
96 kW (129 hp)


**Transmission type**
Automatic

**Steering wheel placement**
LHD

**Engine description**
ENG-4CYL 1.5L TURBO ALU DV5RC (LQP)


**Number of seats**
5


**Engine code**
10Q3AR0057738


**CO2 emissions**
109 g/km


Equipment


As received from the manufacturer


**0**
PARK & GO PACK 1


**10**
WINDOW TYPE SOLAR ABSORBING


**12**
CHILD RR SEAT REINFORCED


**14**
AIR.FRT DR&CO SIDE&ROOF FRT&RR


**16**
REINFORCED HEATING ELECTRIC


**18**
LAMP INTR AMBIENT

**2**
SEAT FRONT BENCH WITH H/REST

**21**
COVER CARGO FABRIC

**23**
DUAL ZONE ELEC CLIMATE CONTROL

**25**
SIGHT & LIGHT PACK 1 PACKAGE

**27**
ADJUSTABLE DRIVER'S ARMREST

29
SUNSHADE DRIV&PASS W/MIRROR&CO

30
TRAY FRT FLR CONS CUP HOLDER

32
VEHICLE FUEL DIESEL B10

34
PACKAGE TRIM LEVEL 2 (DYNAMIC)

36
TRIM CLOTH LEV 2.1 JET BLACK

38
RADIO INTELLILINK RF900 TOUCH

4
ISOFIX - FRONT PASSENGER SEAT

41
CRUISE CNTRL AUTO ELEC. SPEED

43
HEATER DUCT RR (2ND POSN)

45
REFRIGERANT LOW GWP

47
LEFT HAND DRIVE

49
TRANS-AUTO 8-SPEED 8G30 GEN4

50
MARKETING AREA - EUROPE

52
TRANS-AUTO MERCHANDISED EQU.

54
MAN.TILT TELESCOPING STEERING

56
EMISSION SYSTEM EURO 6D-TEMP

58
MODEL UPGRADE 02

6
DRIVER'S SEAT HEIGHT ADJUSTER

61
MDL.YR.C-PLT.TRIAL

63
WHL SPARE 18X4.0 B STEEL DES1

65
LAMP FRT FOG ECE

67
HEADL. CNTRL AUTOM ON-OFF

69
CONTROL INTELLIGENT HIGH BEAM

70
STOLAMP CENTER HIGH MOUNTED

72
HORN SINGLE NOTE

74
INFORMATION-COMPUTER

76
FRONT AND REAR PARKING SENSORS

78
LOCATING SYST. GPS NOT INSTALL

8
RESTRAINT HEAD FRT SEAT UP/D

81
INDIC. SEAT BELT WARNING RR

83
INDICATOR ST BELT WARNING PASS


85
ANTENNA - DIVERSITY


87
6 LOUDSPEAKERS CUSTOM


89
GEARING CODE


90
VIN MODEL YEAR 2019


92
LUGGAGE CARRIER ROOF ALUMINUM


**1**
INTERIOR TRIM JET BLACK


**11**
REAR CENTER HEAD RESTRAINT


**13**
VEHICLE TYPE PASSENGER CAR


**15**
WASHER + WIPER BACK WINDOW


**17**
GLAZED REAR DOOR W/WASHER+HEAT


**19**
PASSENGER AIRBAG MANUAL CUTOFF

**20**
WIPER SYS MOISTURE SENSITIVE

**22**
PSA SALES REGION PKG - GRP 01

**24**
ITALY-MANDATORY

**26**
HANDLE O/S DR COLORED

**28**
MIRROR IS/RV LT SENSITIVE

3
RESTRAINT SEAT BELT TENSIONER

31
MIR O/S RC EL HT CNVX PWRF PUD

33
ELECTRONIC STABILITY PROGRAMME

35
MOONSTONE GREY

37
ENGINEERING YEAR 2019

39
ABS 16" FRT & RR DISC POWER

40
BRAKE PARKING POWER OPERATED

42
HILL START ASSIST

44
START/STOP ENGINE CONTROL

46
KEY PRIMARY FOLDABLE ADD FOLD

48
ENG-4CYL 1.5L TURBO ALU DV5RC

5
SEAT HEIGHT ADJUSTER

51
MOLDING B/S UPPER BLACK

53
STEERING WHEEL LEATH. 3 SPOKES

55
MANUAL CHILD LOCK SYSTEM

57
POWER STEER NON VAR ELECTRIC

59
TRIM LEVEL STEERING V2

60
TYR ALL215/65R17SL99V BW HW1 1

62
WHEEL 17X7 J ALU DESIGN 1

64
RESTR SEAT BELT PRETENS RR

66
HEADLAMPS HALOGEN

68
TRIM CLOTH LEV 2.1 JET BLACK

7
WINDSHIELD ACOUSTIC PVB

71
LAMP INTERIOR ROOF RR COURTESY

73
SPEEDOM. KM

75
CONTROL STEERING WHEEL RADIO

77
INFO DISPLAY MULTI COLOR GRAPH

79
FRT CAMERA+LANE DEPARTURE WARN

80
LAMP REAR TAIL LED

82
INDICATOR ST BELT WARNING DRIV

84
TPMS - TYRE PRESSURE MONITOR

86
SENSOR TRAFFIC SIGN RECOGNITIO

88
VEHICLE STATEMENT ECE ORG

9
PROVISIONS FOR RESTRAINING NET

91
TYR SPARE 135/80R18 SL104V BW1


93
WITHOUT WAX PROTECTION

Timeline

7 records found

The timeline of records for this vehicle

Records

01/2019  Country unknown

Was manufactured
The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

01/2019 Country unknown

First registration
The record represents an administrative event. This could be related to a change of ownership, documents, etc

01/2019 Italy

Was registered
The record represents an administrative event. This could be related to a change of ownership, documents, etc

01/2023 Italy

Was inspected
A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

10/2024 Italy

Was on sale
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

11/2024 Italy

Was deregistered
The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.

04/2025 Poland

Was on sale
This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location.

 +31 **Data sources**
We checked 900+ data sources in 35 countries