

DS

VIN: VR1JCYHZRLY049779

Generated on 05/20/2025, 05:54 PM

Scan for full report

Purpose

✓ Looks good

Odometer

✓ Looks good

Legal status

✓ Looks good

Damage

✓ Looks good

+31 **Data sources**
We checked 900+ data sources in **35 countries**

Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

✓

No issues found

No records of vehicle being used in irregular manner

Here's what we checked:

Taxi ✓ No record found No evidence of being used as a taxi

Transport ✓ No record found No evidence of being used as a transport vehicle

Rental ✓ No record found No evidence of being used as a rental vehicle

Police ✓ No record found No evidence of being used by police

Demo ✓ No record found No evidence of being used as a demo vehicle

Driving school vehicle ✓ No record found No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

✓

No issues found

We didn't find any records that the vehicle was stolen.

Note
Police database stolen vehicle check completed in **11 countries**: +5

Here's what we checked:

Currently wanted as stolen ✓ No record found

Stolen in the past ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle check completed in:

United States

Italy

Denmark

Romania

Lithuania

Sweden

Hungary

Czechia

Slovakia

Slovenia

Canada

Odometer

Are there signs of mileage rollbacks or discrepancies?

Note

- Last known mileage: 11 km
- 1 mileage record found

Odometer records	
12/2020	11 km

Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

✓

No issues found

No records about the legal status of this vehicle were found

Legal

Technical inspection (MOT) ✓ No record found No technical inspection records found

Scrap ✓ No record found No record that vehicle was marked as scrapped

Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

✓

No issues found

Damage records

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

✓

No issues found

Vehicle's location was not recorded in the area of a natural disaster

Emissions

How much CO2 emissions do vehicles of this model/year produce?

carVertical Insight
This vehicle has low emissions. It may qualify for lower emission taxes. Check local regulations to see if discounts apply.

CO₂ emissions

Emission CO₂ g/km

Up to 120

120 - 140

140 - 155

155 - 165

165 - 190

190 - 225

225 +

Your vehicle CO₂ emissions

100 g/km

Class **A**

Specs

What specs and equipment are on record for this vehicle?

Note
Check whether the specs and equipment of this vehicle match the facts given by the seller.

Identification and technical specifications

Make
DS

Powertrain displacement
1.5 L

Powertrain power
96 kW (129 hp)

Number of seats
5

CO2 emissions
100 g/km

Timeline

2 records found

The timeline of records for this vehicle

Records

12/2020 Italy

First registration
The record represents an administrative event. This could be related to a change of ownership, documents, etc

11/2024 Italy

Was deregistered
The indicated record represents an administrative event. This could be related to a change of ownership, change of documents, or similar.

+31 **Data sources**
We checked 900+ data sources in **35 countries**