



**Mercedes-Benz E 320**  
VIN: WDBUF65J85A625234 Gasoline


  
Scan for full report


Generated on 05/19/2025, 06:30 PM



**Purpose**  
Looks good

**Odometer**  
Needs attention

**Legal status**  
Looks good


**Title check**  
Needs attention

**Damage**  
Needs attention



  +31 **Data sources**  
We checked 900+ data sources in 35 countries



## Purpose



Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!



**No issues found**  
No records of vehicle being used in irregular manner



Here's what we checked:



**Taxi**  No record found No evidence of being used as a taxi

**Transport**  No record found No evidence of being used as a transport vehicle

**Rental**  No record found No evidence of being used as a rental vehicle

**Police**  No record found No evidence of being used by police







**Demo**  No record found No evidence of being used as a demo vehicle

**Driving school vehicle**  No record found No evidence of being used as a driving school vehicle



## Theft



Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

**No issues found**  
We didn't find any records that the vehicle was stolen.


**Note**  
Police database stolen vehicle check completed in 11 countries:      +5


Here's what we checked:


**Currently wanted as stolen**  No record found


**Stolen in the past**  No record found No past theft records found for this vehicle.


Police database stolen vehicle check completed in:


**United States**


**Lithuania**


**Slovakia**


**Sweden**


**Slovenia**


**Canada**

**Hungary**

**Italy**


**Romania**


**Denmark**

**Czechia**


## Odometer


Are there signs of mileage rollbacks or discrepancies?

**Beware**  
This vehicle may have a fake mileage!

**Note**

- Last known mileage: 254,408 km
- 8 mileage records found




Odometer records	
01/2005	1,414 km
10/2013	98,997 km
01/2016	313,264 km
12/2017	128,635 km  Odometer Rollback
07/2018	141,548 km




Odometer records	
12/2019	192,521 km
01/2022	230,510 km
07/2024	254,408 km



## Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

**No issues found**  
No records about the legal status of this vehicle were found


### Legal


**Technical inspection (MOT)**  07/2024  Has successfully passed technical inspection  
Valid until 07/2026

**Scrap**  No record found No record that vehicle was marked as scrapped


## Title check

Is the vehicle marked with the branded title "Junk," "Salvage," "Flood," or others? Note: these are official title brand terms recognized by US state agencies


**Beware**  
Salvage title found!


**Note**  
Vehicles with the "Salvage" title cannot be registered for road use without extensive repairs


## Title brands


**Salvage**  01/2005

**Junk**  No record found

**Fire**  No record found


**Flood**  No record found


**Hail**  No record found

**Lemon**  No record found


58 Title brands were checked

## Odometer brands


**Actual**  No record found

**Not Actual**  No record found


**Exceeds Mechanical Limits**  No record found

**Maybe Altered**  No record found

**Tampering**  No record found


**Exempt Odometer Disclosure**  No record found


11 Odometer brands were checked

**Note**  
The certificate of title (also known as a "car title") is a legal document that establishes ownership of a vehicle in the United States. Vehicle titles are "branded" to note certain events in a vehicle's history, such as various types of damage, mileage rollbacks, warranty events, and more.


## Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

**Beware**  
We found 3 records for this vehicle


**Note**  
Mild damages normally won't impact a vehicle's safety or leave structural issues

## Damage records




Left side  
Front  
Right side  
Rear

Damaged parts unclassified


01/2005 

**Damage**  
Estimated Repair Cost  
**Unknown**  
Possible Cause  
**Unknown**




Left side  
Front  
Right side  
Rear

Front damages: Front / Bumper Front right / Bumper


01/2015 

**Assessment**  
Sides affected  
Front  
Estimated Repair Cost  
**€0 – €500**  
Possible Cause  
**Unknown**  
Damage Groups  
Exterior body parts



Left side  
Front  
Right side  
Rear

Left side damages: Left / Front door  
Front damages: Front / Bumper Front left / Bumper  
Other damages: Front right / Bumper  
Roof / Structure

07/2018 

**Assessment**  
Sides affected  
Left side Front  
Estimated Repair Cost  
**€501 – €1,500**  
Possible Cause  
**Unknown**  
Damage Groups  
Exterior body parts  
Structural elements of the body


**Disclaimer:** Most damage records are related to accidents, but that's not always the case. Some records come from other sources like body shops, damage claims, auctions, or vehicle inspections. These records show that the vehicle's condition was assessed, even if it wasn't due to an accident.

**Damage Glossary**  
**Assessment**  
Assessment is the process of evaluating the extent of damage to a vehicle. It involves inspecting the vehicle to determine what repairs are needed, estimating the costs, and deciding whether the vehicle is repairable or considered a total loss.  
**Damage**  
Damage refers to any physical harm or loss sustained by a vehicle, such as scratches, dents, or broken parts. It can result from accidents, weather, theft, or other incidents and may affect the car's appearance or performance.  
**Estimated Repair Cost**  
Once an incident related to a vehicle is assessed, damage data providers calculate the repair cost and present it in the currency of the country where the damage was evaluated. Therefore, this may not align with your expectations. The reasons for this may include:

- The country or state where damage to the vehicle was assessed may have higher/lower servicing costs compared to your country (spare part prices and labor prices differ between countries)
- The cost is calculated for repairs at an official service station (which is typically on the expensive end)


## Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?


**No issues found**  
Vehicle's location was not recorded in the area of a natural disaster


## Specs & equipment


What specs and equipment are on record for this vehicle?


**Note**  
Check whether the specs and equipment of this vehicle match the facts given by the seller.


## Identification and technical specifications

**Make**  
Mercedes-Benz

**Model**  
E 320

**Description**  
E 320

**Body type**  
Sedan

**Powertrain displacement**  
3.2 L

**Fuel type**  
Gasoline

**Transmission type**  
Automatic

**Number of gears**  
5

**Engine code**  
M112

## Equipment

As received from the manufacturer

**130A**  
MB TEX-LEATHER, TWIN/ARTICO

**138A**  
MB TEX-LEATHER, TWIN/ARTICO - GRAY

**212B**  
OP. INSTRUCT. AND MAINT. BOOKLET-ENGL. FOR USA/CAN

**213**  
SPEED-SENSITIVE POWER STEERING/VARIO STEERING

**21N**  
STEUERCODE WERK SINDELINGEN/GRAZ

**221B**  
SIGN COOLANT/REFUELING - ENGLISH

**232**  
GARAGE DOOR OPENER WITH 284 - 390 MHZ FREQUENCY

**23N**  
STEUERCODE WERK SINDELINGEN/GRAZ

**242**  
FRONT SEAT RH ELECTRIC ADJUSTABLE WITH MEMORY

**249**  
INSIDE AND OUTSIDE MIRROR AUTOMATIC DIMMING

**264**  
LICENSE PLATE ATTACHMENT AMERICA

**265**  
LINES-NO.PLATE DISCONTINUED

**275**  
MEMORY PACKAGE (DRIVER SEAT, STRG. COL., MIRROR)

**280**  
LEATHER STEERING WHEEL AND LEATHER GEAR SHIFT KNOB

**284B**  
AIRBAG LABEL - ENGLISH FOR USA

**28N**  
STEUERCODE WERK SINDELINGEN/GRAZ

**293**  
SIDE BAG IN REAR LEFT AND RIGHT

**297**  
SUN BLIND IN REAR DOORS LH AND RH

**308**  
CUP HOLDER

**359**  
LOW COST TELEAID USA

**414**  
ELECTRIC TILT/SLIDE SUNROOF IN GLASS VERSION

**423**  
5-SPEED AUTOMATIC TRANSMISSION

**461**  
INSTRUMENT WITH MILES IND. AND ENGLISH LEGEND U.S. VERSION

**494**  
COMAND DVD PLUS (WITHOUT NAVIGATION)

**524**  
PRODUCT PROT. F. PAINT - TRANSPORT VEH. PRESERVATION

**528**  
SUN VISOR WITH MAKE-UP MIRROR L. AND R., BE-

**540**  
ROLLER BLIND, ELECTRIC, FOR REAR WINDOW

**543**  
CHILD SEAT MOUNTING, ISOFIX IN REAR

**551**  
ANTI-THEFT/ANTI-BREAK-IN WARNING SYSTEM

**573**  
DELETION - FIRST AID KIT

**580**  
AIR CONDITIONER

**634**  
PRODUCT PROT. F. TRANSPORT VEH. W/ TIE-DOWN HOOKS

**636**  
DELETION - WARNING TRIANGLE

**668**  
HIGH-CAPACITY BATTERY

**672**  
LIGHT-ALLOY-WHEEL 5-STAR DESIGN

**673**  
UNITED STATES (USA)

**690**  
EMERGENCY SPARE TIRE (MINI SPARE)

**706L**  
RADIO REMOTE CONTROL W/ PANIC SWITCH (315 MHZ)

**723U**  
CUBANITE SILVER - METALIC

**763**  
YEAR OF MODIFICATION

**7XXL**  
NORTH AND SOUTH AMERICA

**805**  
SEAT HEATER FOR LEFT AND RIGHT FRONT SEATS

**819**  
CD CHANGER

**873**  
DYNAMO WITH HIGHER CAPACITY (FFO)

**875**  
HEATED SCREEN WASH SYSTEM

**910**  
AIRCON COOLING POWER PACKAGE

**915**  
FUEL TANK WITH LARGER CAPACITY

**986**  
IDENTIFICATION NUMBER (VIN-NO.)

**955**  
EQUIPMENT PACKAGE ELEGANCE

**M112**  
V6-GASOLINE ENGINE M112

**989**  
IDENTIFICATION LABEL UNDER WINDSHIELD

**M112**  
CAPACITY 3,2 LITER

## Timeline

11 records found

The timeline of records for this vehicle

## Records

01/2005 

**Damage detected** 

We have indications that this vehicle was recognised as damaged in this particular country (or state). Please refer to the "Damage" section for detailed details.

01/2005 

**Was registered**

The record represents an administrative event. This could be related to a change of ownership, documents, etc

01/2005 

**Had title changed**

This vehicle has had its title changed in this state. This could be related to a change of ownership, technical condition, or similar.

10/2013 

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

01/2015 

**Assessment detected** 

We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

01/2016 

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

12/2017 

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

07/2018 

**Assessment detected** 

We have indications that this vehicle underwent an assessment in this country (or state). Please refer to the "Damage" section for detailed information.

12/2019 

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

01/2022 

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed