

### Skoda Octavia

VIN: TMBLK9NE0L0039871

Diesel

2019

Scan for full report

**Purpose**

✓ Looks good

**Odometer**

✓ Looks good

**Legal status**

✓ Looks good

**Damage**

✓ Looks good

+31

**Data sources**  
We checked 900+ data sources in 35 countries

## Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

✓

**No issues found**  
No records of vehicle being used in irregular manner

Here's what we checked:

- Taxi** ✓ No record found No evidence of being used as a taxi
- Transport** ✓ No record found No evidence of being used as a transport vehicle
- Rental** ✓ No record found No evidence of being used as a rental vehicle
- Police** ✓ No record found No evidence of being used by police
- Demo** ✓ No record found No evidence of being used as a demo vehicle
- Driving school vehicle** ✓ No record found No evidence of being used as a driving school vehicle

## Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

✓

**No issues found**  
We didn't find any records that the vehicle was stolen.

**Note**  
Police database stolen vehicle check completed in 11 countries: +5

Here's what we checked:

- Currently wanted as stolen** ✓ No record found
- Stolen in the past** ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle check completed in:

- United States
- Czechia
- Hungary
- Denmark
- Lithuania
- Slovenia
- Slovakia
- Canada
- Romania
- Italy
- Sweden

## Odometer

Are there signs of mileage rollbacks or discrepancies?

**Note**

- Last known mileage: 129,525 km
- 6 mileage records found



## Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

✓

**No issues found**  
No records about the legal status of this vehicle were found

Legal

- Technical inspection (MOT)** ✓ No record found No technical inspection records found
- Scrap** ✓ No record found No record that vehicle was marked as scrapped

## Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

✓

**No issues found**

**Damage records**

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

## Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

✓


**No issues found**  
Vehicle's location was not recorded in the area of a natural disaster

## Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

**Note**

- Average market price for such vehicle: €16,489
- Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!



## Specs

What specs and equipment are on record for this vehicle?

**Note**  
Check whether the specs and equipment of this vehicle match the facts given by the seller.

## Identification and technical specifications

- Make**  
Skoda
- Model**  
Octavia
- Body type**  
Estate
- Manufacture year**  
2019
- Model year**  
2020
- Powertrain displacement**  
2 L
- Fuel type**  
Diesel
- Transmission type**  
Automatic
- Drive type**  
AWD
- Number of doors**  
5
- Number of cylinders**  
4
- Number of gears**  
7
- Model market**  
Europe
- Number of seats**  
5
- Engine code**  
DJGA

## Timeline

1 record found

The timeline of records for this vehicle

**Records**

01/2019 Country unknown

**Was manufactured**

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the manufacturer. The date may be approximate.

+31

**Data sources**  
We checked 900+ data sources in 35 countries