





**Mercedes-Benz 200**  
VIN: WDD2130131A103239 Diesel  
Generated on 05/08/2025, 09:12 AM





Scan for full report

**Purpose**  
✔ Looks good

**Odometer**  
⚠ Needs attention

**Legal status**  
✔ Looks good


**Damage**  
⚠ Needs attention

**Data sources**  
+31  
We checked 900+ data sources in 35 countries

## Photos


We found 8 photos of this vehicle. Scan report QR code to see all.

03/2024





## Purpose


Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!


**No issues found**  
No records of vehicle being used in irregular manner


Here's what we checked:


**Taxi** ✔ No record found No evidence of being used as a taxi

**Transport** ✔ No record found No evidence of being used as a transport vehicle

**Rental** ✔ No record found No evidence of being used as a rental vehicle


**Police** ✔ No record found No evidence of being used by police




**Demo** ✔ No record found No evidence of being used as a demo vehicle

**Driving school vehicle** ✔ No record found No evidence of being used as a driving school vehicle

## Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

**No issues found**  
We didn't find any records that the vehicle was stolen.


**Note**  
Police database stolen vehicle check completed in 11 countries:     +5


Here's what we checked:


**Currently wanted as stolen** ✔ No record found


**Stolen in the past** ✔ No record found No past theft records found for this vehicle.


Police database stolen vehicle check completed in:


 Lithuania


 United States


 Slovakia


 Italy


 Czechia


 Romania

 Hungary

 Slovenia


 Sweden


 Canada


 Denmark


## Odometer


Are there signs of mileage rollbacks or discrepancies?

**Beware**  
This vehicle may have a fake mileage!


**Note**  
• Last known mileage: 21,961 km  
• Average mileage for similar models: 153,453 km

**Rollback**



**Note**  
Odometer records


Date	Mileage (km)
12/2016	12
08/2017	22,500
04/2018	47,151
09/2018	65,527
03/2019	83,862
10/2019	102,151
06/2020	125,875
09/2020	135,000
06/2021	137,125
12/2021	150,367
03/2022	159,500
08/2022	169,673
03/2023	187,989
12/2023	213,004
02/2024	217,427
08/2024	21,961


**Note**  
• 16 mileage records found



**Rollback**


## Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

**No issues found**  
No records about the legal status of this vehicle were found


**Legal**


**Technical inspection (MOT)** **Passed** 02/2024  Poland Has successfully passed technical inspection

**Scrap** ✔ No record found No record that vehicle was marked as scrapped


## Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

**Beware**  
We found 3 records for this vehicle


**Note**  
Mild damages normally won't impact a vehicle's safety or leave structural issues

## Damage records




Left side  
Right side  
Rear  
Front

Front damages: **Front / Bumper** **Front left / Bumper**


08/2017 

**Assessment**  
Sides affected  
**Front**  
Estimated Repair Cost  
**€0 – €1,500**  
Possible Cause  
**Direct payment by insurer**  
Description  
The value of the insurer's direct payment based on the damage assessment.




Left side  
Right side  
Rear  
Front

Front damages: **Front / Bumper**


09/2020 

**Assessment**  
Sides affected  
**Front**  
Estimated Repair Cost  
**€501 – €1,500**  
Possible Cause  
**Assessment and value agreement**  
Description  
Damage value that was assessed and agreed-upon by all parties.




Left side  
Right side  
Rear  
Front

Rear damages: **Rear left / Bumper**

03/2022 

**Assessment**  
Sides affected  
**Rear**  
Estimated Repair Cost  
**€501 – €1,500**  
Possible Cause  
**Assessment and value agreement**  
Description  
Damage value that was assessed and agreed-upon by all parties.

**Disclaimer:** Most damage records are related to accidents, but that's not always the case. Some records come from other sources like body shops, damage claims, auctions, or vehicle inspections. These records show that the vehicle's condition was assessed, even if it wasn't due to an accident.

**Damage Glossary**


**Assessment**  
Assessment is the process of evaluating the extent of damage to a vehicle. It involves inspecting the vehicle to determine what repairs are needed, estimating the costs, and deciding whether the vehicle is repairable or considered a total loss.

**Estimated Repair Cost**  
Once an incident related to a vehicle is assessed, damage data providers calculate the repair cost and present it in the currency of the country where the damage was evaluated. Therefore, this may not align with your expectations. The reasons for this may include:

- The country or state where damage to the vehicle was assessed may have higher/lower servicing costs compared to your country (spare part prices and labor prices differ between countries)
- The cost is calculated for repairs at an official service station (which is typically on the expensive end)


## Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

**No issues found**  
Vehicle's location was not recorded in the area of a natural disaster

## Market value

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

**Note**  
• Last known selling price: €20,400  
• Average market price for such vehicle: €16,889  
• Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

## Mercedes-Benz 200 market value today

Market value is determined by examining the price of a particular car model (manufactured in the same year) in the country where the report was generated. We analyze data from the last 6 months.



## Market price history




Price records	
03/2024	€21,800
08/2024	€20,400


## Specs & equipment


What specs and equipment are on record for this vehicle?


**Note**  
Check whether the specs and equipment of this vehicle match the facts given by the seller.


## Identification and technical specifications


**Make**  
**Mercedes-Benz**


**Model**  
**200**


**Description**  
**E 200 D Sedan**


**Variant**  
**d**


**Body type**  
**Sedan**


**Model year**  
**2016**


**Powertrain displacement**  
**2 L**

**Powertrain power**  
**110 kW (148 hp)**


**Fuel type**  
**Diesel**


**Transmission type**  
**Automatic**


**Drive type**  
**RWD**

**Steering wheel placement**  
**LHD**


**Number of cylinders**  
**4**


**Number of gears**  
**9**


**Number of seats**  
**5**


**Equipment**


As received from the manufacturer


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**

**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**


**Equipment**

**Equipment**

**Equipment**

**Equipment**

**Equipment**

**Equipment**

**Equipment**

**Equipment**