

Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

Natural disasters

No issues found

Market value

Note

CARVERTICAL

Emissions

carVertical Insight

CO₂ emissions Emission CO₂ g/km

Up to 120 120 - 140

140 - 155

155 - 165

Note

Ford Model Mondeo

Body type **Estate**

2018

Model year 2018

Manufacture year

Number of seats

01/2018 🚱 Country unknown Was manufactured

01/2018 🚱 Country unknown First registration

Has the vehicle's location been recorded in the area of a natural disaster?

Average market price for such vehicle: €14,694

Ford Mondeo 2018 market value today

How much CO2 emissions do vehicles of this model/year produce?

Your vehicle CO2

emissions 123 g/km

What specs and equipment are on record for this vehicle?

Identification and technical specifications

Vehicle's location was not recorded in the area of a natural disaster

How much was the vehicle sold for in the past? What is the price of vehicles of this year and model on average?

Be cautious of hidden issues if the vehicle was on sale for significantly less than the current price!

VIN: WF0FXXWPCFHD74569 | Generated on 06/09/2025 | Expires on 07/09/20
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

Market value is determined by examining the price of a particular car model (manufactured in the same

VIN: WF0FXXWPCFHD74569

Generated on 06/09/2025 Expires on 07/09/2025

Highest price

€16,123

Damage

No issues found

Damage records

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates

Left side

No damage found

Right side

Front

year) in the country where the report was generated. We analyze data from the last 6 months. Lowest price Average price €14,694 €13,564

This vehicle has average emissions. It will likely incur standard emission taxes.

165 - 190 190 - 225 225 + Specs

Check whether the specs and equipment of this vehicle match the facts given by the seller.

VIN: WF0FXXWPCFHD74569

WIN. WHUFAXWPCFHD/4569 | Generated on 06/09/2025 | Expires on 07/09/20
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

The country (or state) indicates either the location of the manufacturing facility, assembly plant, or registration address of the

VIN: WF0FXXWPCFHD74569 | Generated on 06/09/2025 | Expires on 07/09/2025

Generated on 06/09/2025 | Expires on 07/09/2025

VIN: WF0FXXWPCFHD74569

VIN: WHUFXXWPCFHD74569 | Generated on 06/09/2025 | Expires on 07/09/20
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created.

The record represents an administrative event. This could be related to a change of ownership, documents, etc

Generated on 06/09/2025 | Expires on 07/09/2025

Powertrain displacement Powertrain power 110 kW (148 hp) Transmission type **Automatic**

Records

CO2 emissions 123 g/km Timeline 6 records found The timeline of records for this vehicle

manufacturer. The date may be approximate.

✓= O= Was inspected

12/2024 () Italy documents, or similar. Data sources

+36

CARVERTICAL

We checked 900+ data sources in 40 countries

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included. 11/2024 () Italy Was on sale This record was created because the vehicle was listed for sale on a certain marketplace. Sometimes the vendor's country (or state) overwrites the vehicle's actual location. Was deregistered The indicated record represents an administrative event. This could be related to a change of ownership, change of

01/2018 () Italy ₩as registered The record represents an administrative event. This could be related to a change of ownership, documents, etc CARVERTICAL VIN: WFUFXXWPCFHD/4569 | Generated on 06/09/2025 | Expires on 07/09/20
This PDF report includes only the most essential highlights of the vehicle's history. For the most detailed and up-to-date data, always refer to the digital carVertical report available on our website.
While we take great care to ensure the accuracy and reliability of the data at the time of generation, please note that we cannot guarantee that this PDF file has not been modified or altered after it was created. 11/2023 () Italy