

### Scania

VIN: YS2S4X20005567202 **Diesel**

Generated on 05/20/2025, 11:33 AM

Scan for full report

**Purpose**  
✓ Looks good

**Odometer**  
✓ Looks good

**Legal status**  
✓ Looks good

**Damage**  
✓ Looks good

**Data sources**  
We checked 900+ data sources in **35 countries**

## Purpose

Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

✓

**No issues found**  
No records of vehicle being used in irregular manner

Here's what we checked:

- Taxi** ✓ No record found No evidence of being used as a taxi
- Transport** ✓ No record found No evidence of being used as a transport vehicle
- Rental** ✓ No record found No evidence of being used as a rental vehicle
- Police** ✓ No record found No evidence of being used by police
- Demo** ✓ No record found No evidence of being used as a demo vehicle
- Driving school vehicle** ✓ No record found No evidence of being used as a driving school vehicle

## Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

✓

**No issues found**  
We didn't find any records that the vehicle was stolen.

**Note**  
Police database stolen vehicle check completed in **11 countries**: +5

Here's what we checked:

- Currently wanted as stolen** ✓ No record found
- Stolen in the past** ✓ No record found No past theft records found for this vehicle.

Police database stolen vehicle **check completed in**:


- Lithuania
- United States
- Denmark
- Slovakia
- Czechia
- Romania
- Slovenia
- Hungary
- Italy
- Sweden
- Canada

## Odometer

Are there signs of mileage rollbacks or discrepancies?

**Note**

- Last known mileage: 775,212 km
- 4 mileage records found



## Legal status

Has the vehicle passed technical inspection? Was it marked as scrapped?

✓

**No issues found**  
No records about the legal status of this vehicle were found

Legal

- Technical inspection (MOT)** **Passed** 11/2024 Has successfully passed technical inspection
- Scrap** ✓ No record found No record that vehicle was marked as scrapped


## Damage

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

✓

**No issues found**

### Damage records



Occasional inaccuracies can occur, especially when checking older vehicles. Underground repair shops may illegally disguise vehicle defects or damages, not recording their existence anywhere. Sometimes, even vehicle VIN plates may be replaced. We have a variety of methods to detect even such crimes, but it's impossible to provide a 100% guarantee.

## Natural disasters

Has the vehicle's location been recorded in the area of a natural disaster?

✓

**No issues found**  
Vehicle's location was not recorded in the area of a natural disaster

## Specs

What specs and equipment are on record for this vehicle?

**Note**  
Check whether the specs and equipment of this vehicle match the facts given by the seller.

## Identification and technical specifications

- Make**  
**Scania**
- Powertrain power**  
**331 kW (444 hp)**
- Fuel type**  
**Diesel**
- Number of seats**  
**2**
- Category**  
**n3**
- Gross weight**  
**18,000 kg**
- Curb weight**  
**8,861 kg**

## Timeline

8 records found

The timeline of records for this vehicle

### Records

- 10/2019

**First registration**

The record represents an administrative event. This could be related to a change of ownership, documents, etc
- 12/2019

**Was registered**

The record represents an administrative event. This could be related to a change of ownership, documents, etc
- 09/2022

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.
- 12/2022

**Was insured**

The vehicle was insured in this country (or state). The record may refer to all kinds of insurance (third-party liability, KASKO, etc.) and reinsurance events.

From: 12/02/2022

To: 12/01/2023
- 09/2023

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.
- 12/2023

**Was insured**

The vehicle was insured in this country (or state). The record may refer to all kinds of insurance (third-party liability, KASKO, etc.) and reinsurance events.

From: 12/02/2023

To: 12/01/2024
- 11/2024

**Was insured**

The vehicle was insured in this country (or state). The record may refer to all kinds of insurance (third-party liability, KASKO, etc.) and reinsurance events.

From: 11/22/2024

To: 11/21/2025
- 11/2024

**Was inspected**

A technical inspection event (also known as an MOT, roadworthiness test, or emission control test) has been recorded. Both successful and failed instances may be included.

**Data sources**  
We checked 900+ data sources in **35 countries**