


Purpose

✓ Looks good











Purpose Was the vehicle used as a taxi, rental, or other service vehicle? Note: such vehicles may be in worse condition than usual!

No issues found No records of vehicle being used in irregular manner Here's what we checked:

Taxi ✓ No record found No evidence of being used as a taxi

Transport Von record found No evidence of being used as a transport vehicle

Police V No record found No evidence of being used by police

Demo ✓ No record found No evidence of being used as a demo vehicle

 $\stackrel{\mathsf{Q}}{\hookrightarrow}_{\mathsf{R}}$ Rental \checkmark No record found No evidence of being used as a rental vehicle

Driving school vehicle V No record found No evidence of being used as a driving school vehicle

Theft

Is the vehicle currently marked as stolen? Was it stolen in the past? Has it been recovered?

No issues found

We didn't find any records that the vehicle was stolen.

 $\textbf{Stolen in the past} \quad \checkmark \text{ No record found} \quad \text{No past theft records found for this vehicle.}$



Legal status

No issues found

United States Lithuania Denmark Slovakia Italy Slovenia Romania Hungary

Sweden (*) Canada

Currently wanted as stolen

No record found

Police database stolen vehicle check completed in:

No records about the legal status of this vehicle were found

Has the vehicle passed technical inspection? Was it marked as scrapped?

Legal **Technical inspection (MOT)** ✓ No record found No technical inspection records found

This section helps you understand whether the vehicle was damaged or inspected for damage, along with recorded cost estimates (if available).

Scrap No record found No record that vehicle was marked as scrapped

No issues found


Damage

Damage records

Left side

No damage found





Vehicle's location was not recorded in the area of a natural disaster **Specs**

Make Volvo

Model

Sedan

4

Number of doors

Number of seats

Generation 1.Generation

+31

Natural disasters

No issues found

Has the vehicle's location been recorded in the area of a natural disaster?

Identification and technical specifications

460 Body type

What specs and equipment are on record for this vehicle?

Drive type **FWD**

Check whether the specs and equipment of this vehicle match the facts given by the seller.

Number of cylinders

Gross weight 1,580 kg

We checked 900+ data sources in 35 countries

Data sources